Submit 3 Copies To Appropriate District Office District I	exico Iral Res	ources			Revise	Form C- d March 25, 1			
1625 N. French Dr., Hobbs, NM 87240 District II 811 South First, Artesia, NM 87210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV	OIL CONSERVA 2040 Sout Santa Fe, 2	1	API NO. 30-059- ate Type of TATE	Lease					
2040 South Pacheco, Santa Fe, NM 87505					6. State Oil & Gas Lease No.				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)						7. Lease Name or Unit Agreement Name:			
1. Type of Well: Oil Well Gas Well Other C02 Supply Well						Bravo Dome Carbon Dioxide Gas Unit 1934			
2. Name of Operator					8. Well	No.			
OXY USA Inc. 16696 3. Address of Operator 16696 P.O. Box 50250 Midland, TX 79710-0250 4. Well Location 1000000000000000000000000000000000000					282 9. Pool name or Wildcat Bravo Dome Carbon Dioxide Gas 640				
	1672 feet from the	SOL	<u>ith</u>	line and	2314	_ feet fron	n the€	eastli	ne
Section 28	Township 19		Range	34E	NMPM		County	Union	
	10. Elevation (Show wh		<i>DR, RKI</i> 844'	3, RT, GR, e	etc.)				
11. Check A NOTICE OF INTE PERFORM REMEDIAL WORK	ppropriate Box to Ind NTION TO: PLUG AND ABANDON	_			BSEQUE		ORT OF	-: IG CASING	
	CHANGE PLANS		сомм	ENCE DRILL	ING OPNS	. 🗆	PLUG AN		
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING	TEST AND T JOB)		ABANDC	NMENT	
OTHER:			OTHER	: Completi	on				

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

See	0ther	Side
000	ounci	JIUC

rereby certify that the information above is true and complete to the	best of my knowledge and belief.		<u> </u>
GNATURE Un Staf	_ TITLE_Sr. Regulatory Analyst	DATE J	031/02
/pe or print name David Stewart		Telephone No.	915-685-5717
his space for State use PROVED BY Provenditions of approval, if any:	DISTRICT SUPERV	ISOR _{DATE} //	14/02

BDCDGU 1934-282

08/28/2002 CMIC: Randy Baker

MI x RU SU x PU x R 2 3/8" Tbg x 4.625 Bit x Circ x Wash to 2480' PBTD Displace Hole x Fresh Water x P x LD Tbg x Bit x RD MOSU Prep to Log

09/12/2002 CMIC: Randy Baker

MI x RUWL R Compensated Neutron & Gamma-Ray/CCL Log x LTD 2478' MI x RU SU x R 2 3/8 Tbg to PBTD 2480' x Swb Well Dry x P x LD Tbg x RD x MOSU x Dump 5 BBL 15% HCL Dn Csg MI x RUWL x R 4.0" Perf Gun x Perf x 2218' to 2240' x 2246' to 2296' x 2302' to 2320' x 2332' to 2338' x 2348' to 2358' x 2364' to 2372' x 2392' to 2418' x 2428' to 2440' x 4 SPF x .66" Hole = 608 Holes x Well will not Flow x No Further Report till Frac

09/15/2002 CMIC: Randy Baker Flow Well to Pit x Strong Blow x Drop 6 Soap Sticks x Rec 2 BLW - oil/ diesel Skim x SION

9/16/02

Flow Well to Sales x 700 MCF/Day

9/18/02

Frac Well Dn 5.50 Csg x 287 BBLs 40# Gel x 53 Tons of CO2 containing 608 sx 12/20 mesh SN Well Screened Out on Flush x Left 82 sx SN in Csg x 658' Fill x Flow Well to Pit x Well Died ISIP - 2858 psi x 5 Min SIP - 833 psi x 10 Min SIP - 721 psi x 15 Min SIP 700 psi Max TP - 2858 psi x Avg TP -1480 psi x Avg IR 31 BPM. Prep to Clean Out x Service Unit x Foam Unit x Tuesday 9/24/02

9/23/02

MI x RUSU x Foam Unit x PU x R 2 3/8" Tbg x Notched Collar tag SN @ 1796' x 684' Fill Wash x Ream 1796' to 2480' PBTD x Circ Clean x Rec Large Amount of SN x Cut Foam x Blow well dry Well flowing Strong x Ptg up to 1680 x Flow Well to Clean Up

09/25/2002 CMIC: Randy Baker

Kill Well x 25 BBLs KCL Water x P x LD Remaining Tbg x Notched Collar Remove Frac Valve x Install Production Master Valve Put Well on Prod @ 1.8 MMCF / Day - Rate Increased Overnight