

NEW MEXICO OIL CONSERVATION COMMISSION  
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Oil Exploration, Inc. 1909 First First Natl. Bldg. Oklahoma City, Oklahoma  
(Address)

LEASE Irwin WELL NO. 1-A UNIT S 29 T 21N R 36E

DATE WORK PERFORMED January 20, 1957 POOL South  
SOUTHWEST Clayton

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off  
☐ Beginning Drilling Operations ☐ Remedial Work  
☒ Plugging ☐ Other \_\_\_\_\_

Detailed account of work done, nature and quantity of materials used and results obtained.

In regards to plugging this well, Mr. Roy Short advised me that the bottom of the hole was plugged off. The hole was full of mud. Pipe recovered 1340' of 4". Ten (10) sacks of cement spotted at bottom of surface. Hole was filled within 10' of top of surface with mud. Ten (10) sacks of cement in and at top of surface.

Note: I did not plug any other well on the lease.

If I can be of any further assistance please do not hesitate to call on me.

OIL CONSERVATION COMMISSION

Name \_\_\_\_\_  
Title \_\_\_\_\_  
Date \_\_\_\_\_

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name SKLH  
Position Partner  
Company Dec. Lease Well Service