

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator BRANA CORPORATION	8. Farm or Lease Name Penteco
3. Address of Operator 1223 First Interstate Bldg, 320 Gold SW, Albuquerque, NM 87102	9. Well No. 4
4. Location of Well UNIT LETTER <u>E</u> <u>2600</u> FEET FROM THE <u>North</u> LINE AND <u>1230</u> FEET FROM THE <u>West</u> LINE, SECTION <u>19</u> TOWNSHIP <u>6N</u> RANGE <u>2W</u> NMPM.	10. Field and Pool, or Wildcat Wildcat-Penn.
15. Elevation (Show whether DF, RT, GR, etc.) 5986 Gr.	12. County Valencia



Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to P & A well in the following manner:

Plug #1: 25 sxs of cement from 1720 - 1790"
 Plug #2: 25 sxs of cement from 575 - 645' (Bottom of surface casing)
 Plug #3: 10 sxs of cement @ surface,
 Install regulation P & A marker and clean up location.
 Interval between plugs will be filled with 8.9#/gal gel mud with no corrosive additives.

Clean-up location and fill pits.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED 	TITLE <u>Morris B. Jones, Engineer</u>	DATE <u>7-31-85</u>	
APPROVED BY 	TITLE <u>DISTRICT SUPERVISOR</u>	DATE <u>8-6-85</u>	
CONDITIONS OF APPROVAL, IF ANY:			