

INTER-OFFICE MEMORANDUM

TO:

DATE:

FROM:

SUBJECT:

2. I am inclined to discount the "artesian condition" and believe that well has been partially filled in and that a "trapped water" condition exists.
3. I still believe that a surface plug is adequate and we shouldn't require anything else.
4. Jim Williams would like to observe the clean-out when the plug is placed.

Daw Nutter would like to have our decision on this so that they can inform the Insurance Co. of the required plugging program.

The U.S.G.S. Record for S. F. Railroad well 6.1E.5.412

<u>Jan 1959</u>	<u>change</u>	<u>Highest</u>	<u>Lowest</u>	<u>Record</u>
level day.	1958-59	level year.	level year	began
477.66 28	+0.25'	477.66 59	477.91 58	1957