P. D. BOX 871 SANTA FE, NEW MEXICO

These two wells are located rather close together; neither has been plugged; a partially disassembled cable tool drilling machine was in place over the Northernmost of the two holes, presumably the Ringle Tome No. 3.

An extensive search for the third well failed to reveal its location, there being no section corners, etc., in the area; therefore the status of the Castleberry Tome well is unknown.

Mr. Ringle filed Notice of Intention to plug the Tome No. 1 and Tome No. 2 wells on September 6, 1955. After confirming the location of the wells, these Notices were approved February 9, 1956. No subsequent reports have ever been filed on these wells.

Very truly yours,

DANIEL S. NUTTER, Petroleum Engineer

ga