BW - <u>2</u>

MECHANICAL INTEGRITY TEST (MITs)

DATE:



American Valve & Meter, Inc. 1113 W. BROADWAY P.O. BOX 166 **HOBBS, NM 88240**

TO: Basic

DATE: 09- 22-1

This is to certify that:

1, Bud Collins

, Technician for American Valve & Meter,

Inc., has checked the calibration of the following instrument.

8 "Pressure recorder	Serial No:	110988560012
----------------------	------------	--------------

at these points.

at these po	HIUS.				÷
Pressure _	0-100	5	Temperature		
Test	Found	Left	Test	Found	Left
D		D			"
500		500			
200		<u>20</u> P		· and a second sec	·
1000		1000			
200		200	· <u></u>	The second	
D		Ð			

Remarks:

Signature <u>Gent</u> 10



Submit 1 Copy To Appropriate District Office <u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210 District III	State of New Mexico Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION	Form C-103 October 13, 2009 WELL API NO. 30-025-26884 5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	STATE FEE xx 6. State Oil & Gas Lease No.
87505		
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.)	ES AND REPORTS ON WELLS LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A TION FOR PERMIT" (FORM C-101) FOR SUCH	 Lease Name or Unit Agreement Name Eunice No # 001 BW - 002
1. Type of Well: Oil Well G	as Well 📃 Other Brine	8. Well Number # 1
2. Name of Operator BASiC Energy Services L.P.		9. OGRID Number
3. Address of Operator 801 Cherry	Street Ft Worth, TX 76102	10. Pool name or Wildcat Salado
4. Well Location		
Unit Letter <u>O:630</u> fee	t from the <u>South</u> line and <u>2427</u> feet from the <u>E</u>	Eastline
Section 34	Township 21 S Range 37 E	NMPM County Lea
	11. Elevation (Show whether DR, RKB, RT, GR, etc.,	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JOB I
OTHER:		OTHER: Salado Formation Test
OTHER:		OTHER: Salado Formation Test

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Basic Energy Services L.P. has successfully completed the five year MIT requirement.

Please accept our chart with this C-103 of the event that took place on 8/9/16 Starting time at 8:00 am and Finishing at 12:10 pm 8/9/16.

Mark Whitaker was witness to the event.

Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and construction of the second sec	TITLE <u>SENM Fluid Sales MGR</u> DATE <u>8/9</u> ess: <u>david.alvarado @basicenergyservices.com</u> P	<u>/14</u> HONE: <u>575.746 2072</u>
APPROVED BY: Conditions of Approval (if any):	_TITLE	_DATE



=

American Valve & Meter, Inc.

1113 W. BROADWAY

P.O. BOX 166 HOBBS, NM 88240

T0: Basic Energy

DATE: 03/28/16

This is to certify that:

I, Tony Flores, Technician for American Valve & Meter Inc. has checked the calibration of the following instrument.

8 "_Pressure recorder

Ser# 4299

at these points.

]	Pressure #		*	Pressure #	
Test - 0	Found	Left	Test	Found	Left
- 500	- S	- 500	-	-	-
- 700 - 1000	- A	- 700	-	-	-
- 200	- M - E	- 1000 - 200	-	-	-
~ 0		- 0	-	-	-

Remarks:

Signature: Jong Hu





American Valve & Meter, Inc.

1113 W. BROADWAY P.O. BOX 166 HOBBS, NM 88240

TO: Basic

DATE: 09- 22-11

This is to certify that:

1, Bud Collins

_____, Technicism for American Valve & Mieter,

Inc., has checked the calibration of the following instrument.

B"Pressure recorder	Serial No:	110988560012
---------------------	------------	--------------

at these points.

Pressure	0-1000	Temperature	
Test	Found Left	Test	Found Left

	· •				
D		\square	a na agus saonnan 176 na s		
500		500			
200		<u>20</u> p		- <u></u> -	
1000	- <u></u>	1000			
200		200		- <u></u>	
D		10			

Remarks:

Signature Bert Con 26

.



Chavez, Carl J, EMNRD

From:Chavez, Carl J, EMNRDSent:Wednesday, January 12, 2011 6:20 AMTo:'Alvarado, David'; Griswold, Jim, EMNRD; Gonzales, Elidio L, EMNRD; Whitaker, Mark A,
EMNRDCc:Alaniz, Gloria; Sockwell, LynSubject:RE: Eunice # 1 MIT

Glo:

Ok, OCD is good with this year's MITs. Thank you.

Good luck David with that Deer! ©

Carl J. Chavez, CHMM New Mexico Energy, Minerals & Natural Resources Dept. Oil Conservation Division, Environmental Bureau 1220 South St. Francis Dr., Santa Fe, New Mexico 87505 Office: (505) 476-3490 Fax: (505) 476-3462 E-mail: <u>Carl J. Chavez@state.nm.us</u> Website: <u>http://www.emnrd.state.nm.us/ocd/</u>index.htm (Pollution Prevention Guidance is under "Publications")

From: Alvarado, David [mailto:David.Alvarado@basicenergyservices.com] Sent: Tuesday, January 11, 2011 5:28 PM To: Chavez, Carl J, EMNRD; Griswold, Jim, EMNRD; Gonzales, Elidio L, EMNRD Cc: Alaniz, Gloria; Sockwell, Lyn Subject: RE: Eunice # 1 MIT

Here are both Charts once again,

The formation test took place on 1/3/11 and was good. Mark Whitaker was on location on this day. But when I tested the casing to 680 psi I found it to be leaking off and went looking for the loss of psi and found it 22 ft from surface

We excavated the Casing and replaced the csg yesterday and tested it today. I was in contact with Mark Whitaker today.

Gloria will be mailing this information to you in the morning.

Please correspond with Glo while I am off hunting with a stick.

Dave

From: Chavez, Carl J, EMNRD [mailto:CarlJ.Chavez@state.nm.us]
Sent: Tuesday, January 11, 2011 5:45 PM
To: Alvarado, David; Griswold, Jim, EMNRD; Gonzales, Elidio L, EMNRD
Subject: RE: Eunice # 1 MIT

David:

Hi. Please make a copy of the chart with well name, API#, type of MIT, date of MIT, and witness signature(s) for you records and mail to me to file online and in RBDMS well file.

OCD recalls that the prior formation MIT failed; therefore, the casing MIT is good, but Basic now needs to perform a formation MIT to make sure the cavern is good based on the previous formation MIT failure. Please contact the Hobbs District Office to schedule a date and time so they may witness the Formation MIT if possible.

Thank you.

Carl J. Chavez, CHMM New Mexico Energy, Minerals & Natural Resources Dept. Oil Conservation Division, Environmental Bureau 1220 South St. Francis Dr., Santa Fe, New Mexico 87505 Office: (505) 476-3490 Fax: (505) 476-3490 E-mail: <u>CarlJ.Chavez@state.nm.us</u> Website: <u>http://www.emnrd.state.nm.us/ocd/</u>index.htm (Pollution Prevention Guidance is under "Publications")

From: Alvarado, David [mailto:David.Alvarado@basicenergyservices.com]
Sent: Tuesday, January 11, 2011 2:33 PM
To: Chavez, Carl J, EMNRD; Griswold, Jim, EMNRD; Gonzales, Elidio L, EMNRD
Subject: Eunice # 1 MIT

We have completed the MIT on Casing at 440 PSI for 30 Min. I will scan both charts and send to you all.

Question?

Do I take Original charts to Hobbs Office OCD? or Mail to Santa Fe?

I will leave instructions with Rig Supervisor to have RBP pulled out of hole and set and land Tbg. at a depth of 1540 ft as per Dennis Powers's recommendation.

I will take off for three days on my deer bow hunt but will be back Monday the 17th

Guys,

How soon will I get a yes or no on being able to place this well back in production? Reason being ...if I get a green light, I can send one of the lateral pumps to get fixed and have it ready ASAP.

David Alvarado

Office 575.746.2072 Cell 575.513.1238 Fax 575.746.2435

BASIC Energy Services Confidentiality Notice:

The information in this email is confidential. It is intended solely for the addressee. Access to this email by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful.

BASIC Energy Services Confidentiality Notice:

The information in this email is confidential. It is intended solely for the addressee. Access to this email by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful.



STREET PROCESSING POINT



t

Chavez, Carl J, EMNRD

From: Sent: To: Subject: Chavez, Carl J, EMNRD Tuesday, January 11, 2011 4:45 PM 'Alvarado, David'; Griswold, Jim, EMNRD; Gonzales, Elidio L, EMNRD RE: Eunice # 1 MIT

David:

Hi. Please make a copy of the chart with well name, API#, type of MIT, date of MIT, and witness signature(s) for you records and mail to me to file online and in RBDMS well file.

OCD recalls that the prior formation MIT failed; therefore, the casing MIT is good, but Basic now needs to perform a formation MIT to make sure the cavern is good based on the previous formation MIT failure. Please contact the Hobbs District Office to schedule a date and time so they may witness the Formation MIT if possible.

Thank you.

Carl J. Chavez, CHMM New Mexico Energy, Minerals & Natural Resources Dept. Oil Conservation Division, Environmental Bureau 1220 South St. Francis Dr., Santa Fe, New Mexico 87505 Office: (505) 476-3490 Fax: (505) 476-3462 E-mail: <u>CarlJ.Chavez@state.nm.us</u> Website: <u>http://www.emnrd.state.nm.us/ocd/</u>index.htm (Pollution Prevention Guidance is under "Publications")

From: Alvarado, David [mailto:David.Alvarado@basicenergyservices.com]
Sent: Tuesday, January 11, 2011 2:33 PM
To: Chavez, Carl J, EMNRD; Griswold, Jim, EMNRD; Gonzales, Elidio L, EMNRD
Subject: Eunice # 1 MIT

We have completed the MIT on Casing at 440 PSI for 30 Min. I will scan both charts and send to you all.

Question?

Do I take Original charts to Hobbs Office OCD? or Mail to Santa Fe?

I will leave instructions with Rig Supervisor to have RBP pulled out of hole and set and land Tbg. at a depth of 1540 ft as per Dennis Powers's recommendation.

I will take off for three days on my deer bow hunt but will be back Monday the 17th

Guys,

How soon will I get a yes or no on being able to place this well back in production? Reason being ...if I get a green light, I can send one of the lateral pumps to get fixed and have it ready ASAP.

David Alvarado Office 575.746.2072 Cell 575.513.1238 Fax 575.746.2435 BASIC Energy Services Confidentiality Notice:

.

The information in this email is confidential. It is intended solely for the addressee. Access to this email by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful.

.

Griswold, Jim, EMNRD

From:	Donny Collins [dcollins@gandycorporation.com]
Sent:	Thursday, December 23, 2010 11:53 AM
To:	Griswold, Jim, EMNRD
Subject:	Brine Well test Results
Attachments:	EidsonBrine bw004.pdf; QualityBrine bw002.pdf

Here are the results witnessed by Maxey Brown from Hobbs OCD Office

Gandy Corporation

Quality Brine(tatum Brine) BW-002, API # 30-25-28162 Eidson Brine(Wasserhund Brine) BW-004, API # 30-025-26883

Donny Collins dcollins@gandycorporation.com

Chavez, Carl J, EMNRD

From:	Chavez, Carl J, EMNRD
Sent:	Friday, April 23, 2010 6:56 AM
То:	'Alvarado, David'; 'lyn.sockwell@basicenergyservices.com'; 'James Millett'; Clay Wilson; 'Patterson, Bob'; 'gandy2@leaco.net'; 'Gary Schubert'; 'Dan Gibson'
Cc:	VonGonten, Glenn, EMNRD; Griswold, Jim, EMNRD
Subject:	New Mexico UIC Class III Brine Well MIT Scheduling with Completion by September 30, 2010

Gentlemen:

Re:

Basic Energy Services: BW-002 & BW-025 Gandy Corporation: BW-004 & BW-022 Key Energy Services, LLC: BW-028 Mesquite: BW-027 (MITs on 2-Well System Completed this Season) & BW-030 Salty Dog: BW-008 HRC: BW-031

Good morning. It is that time of year again to remind operators that their MITs for this season must be completed by 9/30/2010. The list of operator names w/ associated brine wells are provided above and as in the past, the OCD attempts to schedule MITs logistically on the same day and it in a route with start times that is most efficient in the field.

Operators are aware of the annual formation MIT (4-hr @ 300 psig or less depending on historical pressure and TD of well) and every 5-yrs. or after well workover. EPA MIT (30 min. @ 500 psig). Operators need to review well MIT records to inform OCD-EB of the type of MIT it will run this year and inform OCD-EB of any issues or concerns associated with this season's MIT.

You may access your well information on OCD Online either by API# and/or Permit Number at http://ocdimage.emnrd.state.nm.us/imaging/AEOrderCriteria.aspx and http://www.emnrd.state.nm.us/imaging/AEOrderCriteria.aspx and http://www.emnrd.state.nm.us/imaging/AEOrderCriteria.aspx and http://www.emnrd.state.nm.us/OCD/OCDPermitting/Data/Wells.aspx. For information on New Mexico's UIC Program and http://www.emnrd.state.nm.us/ocd/Publications.htm.

Please contact Jim Griswold at (505) 476-343465 on or before May 7, 2010 to schedule your preferred MIT date and time. Jim will work to finalize the witness schedule with each of you. Thank you in advance for your cooperation.

Copy: Brine Well Files BWs- 2, 4, 8, 22, 25, 27, 28, 30 & 31

Carl J. Chavez, CHMM UIC Program Quality Assurance & Quality Control Officer New Mexico Energy, Minerals & Natural Resources Dept. Oil Conservation Division, Environmental Bureau 1220 South St. Francis Dr., Santa Fe, New Mexico 87505 Office: (505) 476-3490 Fax: (505) 476-3462 E-mail: <u>Carl J. Chavez@state.nm.us</u> Website: <u>http://www.emnrd.state.nm.us/ocd/</u>index.htm (Pollution Prevention Guidance is under "Publications")

Chavez, Carl J, EMNRD

From:Chavez, Carl J, EMNRDSent:Thursday, July 02, 2009 11:48 AMTo:'Prather, Steve'Subject:FW: Chart Request from 6/9/09 MIT Request (BW-2 and BW-25)Attachments:image001.gif

Steve:

Hi. Please disregard the BW-28 highlighted in yellow request below. I need your charts and calibration sheets from your last MITs for BWs 2 and 25.

Thanks.

Carl J. Chavez, CHMM New Mexico Energy, Minerals & Natural Resources Dept. Oil Conservation Division, Environmental Bureau 1220 South St. Francis Dr., Santa Fe, New Mexico 87505 Office: (505) 476-3490 Fax: (505) 476-3462 E-mail: <u>Carl J. Chavez@state.nm.us</u> Website: <u>http://www.emnrd.state.nm.us/ocd/</u>index.htm (Pollution Prevention Guidance is under "Publications")

From: Chavez, Carl J, EMNRD
Sent: Thursday, July 02, 2009 11:09 AM
To: 'Prather, Steve'
Subject: FW: Chart Request from 6/9/09 MIT Request (BW-25)

Steve:

Hi. The OCD also needs the chart and calibration sheet from the EPA 5-Yr. 30 min. MIT conducted on 6/9/2009.

Thank you.

Carl J. Chavez, CHMM New Mexico Energy, Minerals & Natural Resources Dept. Oil Conservation Division, Environmental Bureau 1220 South St. Francis Dr., Santa Fe, New Mexico 87505 Office: (505) 476-3490 Fax: (505) 476-3462 E-mail: <u>CarlJ.Chavez@state.nm.us</u> Website: <u>http://www.emnrd.state.nm.us/ocd/</u>index.htm (Pollution Prevention Guidance is under "Publications")

From: Chavez, Carl J, EMNRD Sent: Thursday, July 02, 2009 9:47 AM To: 'Prather, Steve' Subject: Chart Request from 5/21/09 MIT Request (BW-28)

Steve:

Good morning. Could you please send me the chart from the recent 5/21/09 MIT for our records?

Hope you have a Happy 4th! Thank you.

Carl J. Chavez, CHMM New Mexico Energy, Minerals & Natural Resources Dept. Oil Conservation Division, Environmental Bureau 1220 South St. Francis Dr., Santa Fe, New Mexico 87505 Office: (505) 476-3490 Fax: (505) 476-3462

E-mail: CarlJ.Chavez@state.nm.us

Website: <u>http://www.emnrd.state.nm.us/ocd/</u>index.htm (Pollution Prevention Guidance is under "Publications")

Active Brine Well Facilities

• **BW-2** Basic Energy/P&S Eunice #1 (API 30-025-26884) Began production in July 1980. Depth to top-of-salt 1320 ft bgs. Casing shoe @ 1440 ft bgs. Tubing depth 1718 ft bgs. Last sonar log completed February 2009. Interval imaged 1440 to 1666 ft bgs. Log indicates only 21,000 bbls of cavern volume despite historic production of 6.8 Mbbls. Cavern should be ~1Mbbls. Permit renewal date: 1/6/2014

• BW-4 Gandy Corporation/Eidson State #1 (API 30-025-26883)

Began production in August 1980.

Depth to top-of-salt 1865 ft bgs. Casing shoe @ 1895 ft bgs. Tubing depth 2461 ft bgs. Last sonar log completed October 2008. Interval imaged 1909 to 1944 ft bgs. Log indicates only 11 bbls of cavern volume despite historic production of 5.28 Mbbls. Cavern should be ~800,000 bbls. Permit renewal date: 6/11/2011

• BW-8 PAB Services/Brine Supply #1 (API 30-025-26307)

Began production in May 1979.

Depth to top-of-salt 2000 ft bgs. Casing shoe @ 1871 ft bgs. Tubing depth 2552 ft bgs. Last sonar log completed February 2009. Interval imaged 1871 to 1903 ft bgs. Log indicates only 720 bbls of cavern volume despite historic production of perhaps 12 Mbbls. Cavern should be 1.8 Mbbls. Permit renewal application currently under review.

• BW-22 Gandy Corporation/Watson #1 (API 30-025-28162)

Began production in April 1983.

Depth to top-of-salt 2290 ft bgs. Casing shoe @ 2249 ft bgs. Tubing depth 2870 ft bgs.

Last sonar log completed August 2008. Interval imaged 2200 to 2220 ft bgs. Log indicates only 11,289 bbls of cavern volume despite historic production of perhaps 18 Mbbls. Cavern should be 2.7 Mbbls. Permit renewal date: 3/11/2012

• BW-25 Basic Energy/Salado #2 (API 30-025-32394)

Began production in September 1993.

Depth to top-of-salt 1220 ft bgs. Casing shoe @ 1220 ft bgs. Tubing depth 1385 ft bgs.

No sonar log run. Historic production of perhaps 1.7 Mbbls, indicating cavern volume of 25,500 bbls.

Permit renewal application currently under review.

• BW-27 Mesquite SWD/Dunaway #1 and #2 (APIs 30-015-28083 and 28084)

Began production in January 1995.

Depth to top-of-salt 1060 ft bgs. Casing shoe @ 1064 ft bgs. Tubing depth 1024 ft bgs. Last sonar log attempted December 2008 but failed to get any data due to configuration of casing and tubing. Permit renewal date: 9/21/2009

• BW-28 Key Energy/State Brine Well #1 (API 30-025-33547)

Began production in October 1996.

Depth to top-of-salt 1390 ft bgs. Casing shoe @ 1390 ft bgs. Tubing depth 2074 ft bgs. Sonar log completed 5/20/09. Report not yet provided. Estimated production of perhaps 4 Mbbls. indicating cavern volume of 600,000 bbls.

Permit renewal date: 7/18/2011

• BW-30 Liquid Resource/Hobbs State #10 (API 30-025-35915) Began production in July 2002. Depth to top-of-salt 1645 ft bgs. Casing shoe @ 1633 ft bgs. Tubing depth 1930 ft bgs. OCD did not require them to run sonar due to shortness of operational life. Estimated brine production of 1.4 Mbbls, indicateing cavern may be 207,000 bbls. Permit renewal date: 5/29/2012

• **BW-31** HRC/HRC Schubert 7 #1 (API 30-025-36781) Began production in October 2006. Depth to top-of-salt 1800 ft bgs. Casing shoe @ 1865 ft bgs. Tubing depth 2300 ft bgs. No sonar log run. Estimated production of only 560,000 bbls and thus cavern only 84,000 bbls. Permit renewal date: 6/22/2011

Submit 3 Copies To Appropriate Distric Office	ct State of New Mexico	Form C-103 June 19 2008
District 1 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	WELL API NO. 30 - 525268
1301 W. Grand Ave., Artesia, NM 8821	10 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	$r_{\rm s} = 1220$ South St. Francis Dr. Santa Fe. NM 87505	STATE FEE
1220 S. St. Francis Dr., Santa Fe, NM	03 JAN 12 PM 1 29	o. State off te Gas Bease 110.
SUNDRY NO	OTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESERVOIR. USE "API	PPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A PLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Funce Brine Well 15)
1. Type of Well: Oil Well	Gas Well 🗆 Other Brine	8. Well Number
2. Name of Operator	(Constant	9. OGRID Number
3. Address of Operator		10. Pool name or Wildcat
F.D. Draws	1869 Eunine 88231	
4. Well Location	feet from the (030 ESTime and 2	427 FEC line
Section 34	Township 2/S Range 37 E	NMPM County (- • •
	11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
In Proceedings of the Control of the		
12. Chec	k Appropriate Box to Indicate Nature of Notice, I	Report or Other Data
NOTICE OF	INTENTION TO SUB	SEQUENT REPORT OF
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRIL	
PULL OR ALTER CASING DOWNHOLE COMMINGLE		JOB 🗌
DOWNHOLE COMMINGLE		JOB []
DOWNHOLE COMMINGLE	MULTIPLE COMPL CASING/CEMENT T T Soc OTHER: mpleted operations. (Clearly state all pertinent details and	JOB
DOWNHOLE COMMINGLE [OTHER: Syew MI 13. Describe proposed or con of starting any proposed	MULTIPLE COMPL CASING/CEMENT T + Second OTHER: mpleted operations. (Clearly state all pertinent details, and work). SEE RULE 1103. For Multiple Completions: Att	JOB
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 5 year MI 13. Describe proposed or com of starting any proposed or recompletion.	MULTIPLE COMPL CASING/CEMENT T + Sonar OTHER: mpleted operations. (Clearly state all pertinent details, and work). SEE RULE 1103. For Multiple Completions: Att	JOB
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Syew MI 13. Describe proposed or com of starting any proposed or recompletion. Pull old	MULTIPLE COMPL CASING/CEMENT T + Sonar other mpleted operations. (Clearly state all pertinent details, and work). SEE RULE 1103. For Multiple Completions: Att + Jbing out of hole. Run F	JOB I give pertinent dates, including estimated da ach wellbore diagram of proposed completion
PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Sycar MI 13. Describe proposed or con of starting any proposed or recompletion. Pull old Casing Show, T	MULTIPLE COMPL CASING/CEMENT T + Sonar OTHER: mpleted operations. (Clearly state all pertinent details, and work). SEE RULE 1103. For Multiple Completions: Att + Jbing out of hole. Run F Rule-casing w/chart record	JOB I give pertinent dates, including estimated da ach wellbore diagram of proposed completion SGCSIAN ON WORK SH SA FOR FOR FAN, 3
PULL OR ALTER CASING DOWNHOLE COMMINGLE 13. Describe proposed or con of starting any proposed or recompletion. Pull old Casing Show, T	DITIPLE COMPL CASING/CEMENT T + Sona OTHER: mpleted operations. (Clearly state all pertinent details, and work). SEE RULE 1103. For Multiple Completions: Att + Jbing out of hole. Run F este-casing ws/chort record a back out of hole. In	JOB I give pertinent dates, including estimated da ach wellbore diagram of proposed completion packs on work sho a to 5064 for 3 bit on 3±
PULL OR ALTER CASING DOWNHOLE COMMINGLE 13. Describe proposed or con of starting any proposed or recompletion. Pull old Casing Shoe, T utes. Pull part	Dependence of the set	JOB I give pertinent dates, including estimated da ach wellbore diagram of proposed completion backs on work sho - to 5064 for 3 - to 5064 for 3 - to 32 - to 32
PULL OR ALTER CASING DOWNHOLE COMMINGLE 13. Describe proposed or con of starting any proposed or recompletion. Pull old Casing Shoe, T utes. Pull parts	Determine to Soften of cause	I give pertinent dates, including estimated da ach wellbore diagram of proposed completion back on work sh a to 5064 for 3 stall bit on 3 ty. Parform Sonar
PULL OR ALTER CASING DOWNHOLE COMMINGLE 13. Describe proposed or cou of starting any proposed or recompletion. Pull old Casing Shoe, T utes. Pull part mig and drill	Det wall back of formation	JOB I give pertinent dates, including estimated da ach wellbore diagram of proposed completion packer on work sho a to 500+ for 3 stall bit on 3 in Stall bit on 3 in Chanse old
PULL OR ALTER CASING DOWNHOLE COMMINGLE 13. Describe proposed or cou of starting any proposed or recompletion. Pull old Casing Shoe, T utes. Pull part mig and drill on well.	Dependence of the solution of	JOB I give pertinent dates, including estimated da ach wellbore diagram of proposed completic pack on work sho a to 506# for 3 stall bit on 3 ity. Parform Sonar invoi. Change old
PULL OR ALTER CASING DOWNHOLE COMMINGLE 13. Describe proposed or con of starting any proposed or recompletion. Pull old Casing Shoe, T utes. Pull part ing and drill fob ing out wit	DITIPLE COMPL CASING/CEMENT T + Sonar of OTHER: mpleted operations. (Clearly state all pertinent details, and work). SEE RULE 1103. For Multiple Completions: Att tubing out of hole. Run F restancessing ws/chart record a back out of hole. In down to Softon of cause of wall back a product tubing usef @	I give pertinent dates, including estimated da ach wellbore diagram of proposed completic ogester on work sh a to 500+ for 3 stall bit on 3'± ity. Parform Sonar inv. Change old approx. 1700'
PULL OR ALTER CASING DOWNHOLE COMMINGLE 13. Describe proposed or con of starting any proposed or recompletion. Pull old Casing Shoe, T utes. Pull part and drill ton well, f tobing out wit	Difference of the set	I give pertinent dates, including estimated da ach wellbore diagram of proposed completic paction on work sh a to 500# for 3 oftell bit on 3'E bit on 3'E bit. Parform Sonar from. Change old approx. 1700'
PULL OR ALTER CASING DOWNHOLE COMMINGLE 13. Describe proposed or con of starting any proposed or recompletion. Pull old Casing Shoe, T utes. Pull part and drill to muell, f tobing out with Spud Date:	Determine tubing of a memory of the solution o	Igive pertinent dates, including estimated da ach wellbore diagram of proposed completic pactor on work sh a to 5064 for 3 stall bit on 3± ity. Partom Concr ity. Partom Concr ity. Change old approx. 1700'
PULL OR ALTER CASING DOWNHOLE COMMINGLE 13. Describe proposed or con of starting any proposed or recompletion. Pull old Casing Shoe, T utes. Pull part and drill to mell. A tobing out wit Spud Date:	DITIPLE COMPL CASING/CEMENT T + Sonar of OTHER: mpleted operations. (Clearly state all pertinent details, and work). SEE RULE 1103. For Multiple Completions: Att tubing out of hole. Run F este-casing us/chort records a back out of hole. In down to Softon of cause Off wall back a product the 3t new tubing sef @ Rig Release Date:	I give pertinent dates, including estimated da ach wellbore diagram of proposed completion ogester on work sh a to 506# for 3 stall bit on 3'z ity. Parform Sonar ity. Parform Sonar ity. Change old approx. 1700'
PULL OR ALTER CASING DOWNHOLE COMMINGLE IS DESCRIBE PROPOSED OF COM of starting any proposed or recompletion. Pull old Casing Shoe, T utes. Pull part and drill for well, A fobing out wit Spud Date:	Determine the best of my knowledge	I give pertinent dates, including estimated da ach wellbore diagram of proposed completion of the source of the source of the off of the source of the source of the source of the off of the source of the source of the source of the source of the off of the source of th
PULL OR ALTER CASING DOWNHOLE COMMINGLE I DOWNHOLE COMMINGLE I DOWNHOLE COMMINGLE I DOWNHOLE COMMINGLE I DOSCHOPPODOSED OF COM of starting any proposed or recompletion. Pull old Casing Shoe, T utes. Pull part on well f tobing out with Spud Date:	Deve is true and complete to the best of my knowledge	I give pertinent dates, including estimated data ach wellbore diagram of proposed completion of the source of the
PULL OR ALTER CASING DOWNHOLE COMMINGLE IS DESCRIBE PROPOSED OF COM of starting any proposed or recompletion. Pull old Casing Shoe, T utes. Pull part on well f to well f to well f Spud Date: I hereby certify that the information SIGNATURE	DITILE District MC	I give pertinent dates, including estimated da ach wellbore diagram of proposed completion of the solution of the solution of the solution of the solution of the solution of the solution of the solution of the solution of the solution of
PULL OR ALTER CASING DOWNHOLE COMMINGLE IS DESCRIBE PROPOSED OF COM of starting any proposed or recompletion. Pull old Casing Shoe, T utes. Pull parts on well f tobing out with Spud Date: I hereby certify that the information SIGNATURE	Difference of the set of my knowledge	and belief.
PULL OR ALTER CASING DOWNHOLE COMMINGLE I DOWNHOLE COMMINGLE I DOWNHOLE COMMINGLE I DOWNHOLE COMMINGLE I DOWNHOLE COMMINGLE I DOWNHOLE COMMINGLE I hereby certify that the information SIGNATURE Type or print name For State Use Only	MULTIPLE COMPL CASING/CEMENT T + Sonar D OTHER: mpleted operations. (Clearly state all pertinent details, and work). SEE RULE 1103. For Multiple Completions: Att tubing out of hole. Run F este-casing ws/chort record a back out of hole. In down to Softon of cau Of wall back a product the 3t new tubing stef @ Rig Release Date: TITLE District Mo Store. Proton Product E-mail address: Base Every	I give pertinent dates, including estimated dat ach wellbore diagram of proposed completion of the solution of the solution of the solution of the solution of the solution of the solution of the solution of the solution of the solution of
PULL OR ALTER CASING DOWNHOLE COMMINGLE I OTHER: Syew MI 13. Describe proposed or como of starting any proposed or recompletion. Pull old Casing Shoe, T utes. Pull part on well, A tobing out with Spud Date: I hereby certify that the information SIGNATURE Type or print name For State Use Only APPROVED BY	MULTIPLE COMPL CASING/CEMENT T + Sonar OTHER: mpleted operations. (Clearly state all pertinent details, and work). SEE RULE 1103. For Multiple Completions: Att tybing out of hole. Run F este-casing ws/chort records a back out of hole. In down to Softon of cause Out wall back on product the 3t new tubing seef @ Rig Release Date: TITLE District Mo Store. Protoc	I give pertinent dates, including estimated da ach wellbore diagram of proposed completic ogester on work sh a to 5064 for 3 stall bit on 3'E ity. Parform Conar in Change old approx. 1700' and belief. Mage DATE //9/09 Service PHONE (570.39×.5.



Chavez, Carl J, EMNRD

From: Chavez, Carl J, EMNRD

Sent: Monday, November 10, 2008 1:50 PM

To: 'Prather, Steve'

Cc: Price, Wayne, EMNRD; Hill, Larry, EMNRD

Subject: FW: BW-2 (Eunice No. 1) & BW-25 (Salado Brine Well No. 2) Upcoming MIT & Sonar Testing

Steve:

Hi. BWs-2 and 25 will required the EPA 5-Yr. 30 minute test (pull tubing, set packer near casing shoe (<20 ft. from casing shoe) and pressure up from 300 to 500 psig +/- 10% to pass.

As indicated below, a sonar test is required at BWs-2 and 25, which will facilitate the EPA 5-Yr. MIT before reinstalling the tubing.

Please contact me with your preferred date and time for the MITs and sonar. Thank you.

Carl J. Chavez, CHMM New Mexico Energy, Minerals & Natural Resources Dept. Oil Conservation Division, Environmental Bureau 1220 South St. Francis Dr., Santa Fe, New Mexico 87505 Office: (505) 476-3491 Fax: (505) 476-3462 E-mail: <u>CarlJ.Chavez@state.nm.us</u> Website: <u>http://www.emnrd.state.nm.us/ocd/</u>index.htm (Pollution Prevention Guidance is under "Publications")

From: Chavez, Carl J, EMNRD
Sent: Tuesday, October 21, 2008 2:38 PM
To: 'Prather, Steve'
Cc: Sanchez, Daniel J., EMNRD; Price, Wayne, EMNRD
Subject: BW-2 (Eunice No. 1) & BW-25 (Salado Brine Well No. 2) Upcoming MIT & Sonar Testing

Steve:

Re: OCD August 1, 2008 Letter w/ Brine Well Information Request (BWIR)

Good afternoon. The Oil Conservation Division (OCD) has reviewed Basic Energy Services, LLC responses to the BWIRs for the above subject OCD permitted brine wells. Based on the operational life and volume of brine produced from the above brine wells, sonar testing is required along with your MIT on or before July 31, 2009. According to OCD records, no sonar testing has been conducted on the above subject brine wells to date.

Please contact me within 8 working days to arrange the type, date and time for the MITs and corresponding date for sonar testing. Thank you.

Carl J. Chavez, CHMM New Mexico Energy, Minerals & Natural Resources Dept. Oil Conservation Division, Environmental Bureau 1220 South St. Francis Dr., Santa Fe, New Mexico 87505 Office: (505) 476-3491 Fax: (505) 476-3462 E-mail: <u>CarlJ.Chavez@state.nm.us</u> Website: <u>http://www.emnrd.state.nm.us/ocd/</u>index.htm (Pollution Prevention Guidance is under "Publications")







ľ2



NEW MEXICO MERGY, MINERALS & NATURAL RESOURCES DEPARTMENT



OIL CONSERVATION DIVISION 2040 South Pacheco Street Santa Fe, New Mexico 87505 (505) 827-7131

September 11, 1999

<u>CERTIFIED MAIL</u> <u>RETURN RECEIPT NO. Z 357 870 154</u>

Mr. Paul Prather P&S Brine Sales P.O. Box 7169 Eunice, New Mexico 88231

Re: Mechanical Integrity Testing of Brine Supply Wells

Dear Mr. Paul Prather:

The Underground Injection Control Program of the Federal Safe Drinking Water Act requires that operators demonstrate mechanical integrity of all injection wells by ensuring there are no leaks in the tubing, casing, or packer, and injected/produced fluids are confined within the piping and injection zones.

The Oil Conservation Division (OCD) requires operators of brine supply wells to perform the following mechanical integrity test:

- 1. At least once every five years isolate the cavern formation from the casing/tubing annuals and pressure test the casing at 300 psig for 30 minutes. New brine wells and wells being worked over will have to be tested in this manner before operations begin.
- 2. Annually perform an open hole cavern formation pressure test by pressuring up the formation one and one-half times the normal operating pressure (not to exceed formation fracture pressure) or 300 psig whichever is greater for four hours. Brine supply wells operating with packers will have to pressure both the cavern formation and casing/tubing annuals.

<u>Please find enclosed an OCD Brine Well Test Schedule and Test Procedure for this Fall October</u> 25, 1999 through November 2, 1999. Please have your well ready for testing on the date and <u>time you are schedule</u>. Operators will be responsible for providing equipment and shall bear all costs incurred. All test must be witnessed by the New Mexico Oil Conservation Division.

If you require any further information or assistance please do not hesitate to write or call me at (505-827-7155).

Sincerely Yours,

White Prin

Wayne Price-Pet. Engr. Spec. Environmental Bureau

cc: OCD District Offices attachments- OCD Brine Well Test Schedule & Brine Well Testing Procedure Guidance Document

OCD BRINE WELL TEST SCHEDULE

FALL OF 1999

October 29 1999 9 am 1 pm Pressure test cavern October 29 1999 11 am 3 pm Pressure test cavern November 1 1999 9 am 1 pm Pressure test cavern November 1 1999 9 am 1 pm Pressure test cavern November 1 1999 11 am 3 pm Pressure test cavern	October 29 1999 1 October 29 1999 1 November 1 1999 9	Buckeye Marthon Road Loco Hills SE of Artesia	BW-004 BW-015 BW-021 BW-005	VasserHaun Marathon Brine St. Loco Hills Brine Jims Water Ser.
Image: square for the square for square for the square for the square for the square for	October 27 1999 1:3 October 28 1999 (October 28 1999 1	Warren -McKee #4 Tatum Water St. Crossroads	** BW-001 BW-022 BW-013	Conoco Dality Brine Kenneth Tank Service
October 27 1999 8 am 12 noon Isolate cavern & pressure test casing + Cavern survey October 27 1999 1:30 pm 5:30 pm Isolate cavern & pressure test casing	October 27 1999 1:30 October 27 1999 1:30	Salado Brine St. #2 Warren -McKee #3	** BW-025	Quality Oil (Salado Brine Sales) Conoco
On October 25 1999 11 am 3 pm Pressure test cavern #2 October 26 1999 8 am 12 noon Pressure test cavern + Cavern survey*** October 26 1999 9:30 am 1:30 pm Isolate cavern & pressure test casing + Cavern survey*** October 26 1999 9:30 am 1:30 pm Isolate cavern & pressure test casing + Cavern survey***	October 25 1999 1 October 26 1999 9:30 October 26 1999 9:30	Eunice Brine Station Rowland Truckers #2 Hobbs Station	** BW-018 ** BW-018	Key Energy Scurlock-Permian
• Date of Test Start Stop Type of Test(s) Required , , ler ST. October 25 1999 8 am 12 noon Isolate cavern & pressure test casing + Cavern survey*** m October 25 1999 9:30 am 1:30 pm Isolate cavern & pressure test casing + Cavern survey***	Date of Test Stat	Facility Name Eunice Eunice Water ST Eunice Brine Station	** BW-002 ** BW-009A	Company P&S Brine Simms-McCasland

1

2



Brine Well Testing Procedure Guidance Document

- 1) The cavern and all piping must be filled, pressured up and stabilized for a period of at least 24 hours prior to testing. If this test requires a packer then casing/tubing annulus must be loaded with inert fluid 24 hours prior to testing.
- 2) Have manpower and equipment available for pressure test. Well head shall be prepared for test and all valves and gauges should be in good working order.
- 3) Pressure devices i.e pumps, truck pumps, etc. must be isolated from the well head before and during test.
- 4) A continuous recording pressure chart with an 8 hour clock shall be installed on the casing/tubing annulus. The pressure range shall not be greater than 1,000 psig. The operator must provide proof that the recording device has been calibrated within the past 6 months. Note: Wells with packer installed: If this test requires both the casing/tubing annulus and cavern to be tested then two recording devices must be supplied or one recording device with two pins.
- 5) A minimum of one pressure gage shall be installed in the system.
- 6) OCD must witness the beginning of test (putting chart on) and ending of test (removing chart). At the end of test operator shall bleed-off pressure by 10% to demonstrate recorder response.
- 7) The following information shall be place on the chart:
 - 1. Date, time test started, time stop.
 - 2. Company name, Discharge Plan #, well name and number, legal location UL, section, township, range and county.
 - 3. Type of Test; Open hole, Casing Test, or Both.
 - 4. Printed name and signature of company representative and OCD representative.
- Note: NMOCD recognizes that different operations, well constructions and field conditions may cause variations in the above procedures. If operator wishes to make or anticipate changes please notify the OCD for approval.

OCD Fall of 1999 Brine Well Testing





Date: October 25, 1999 By: Wayne Price-OCD

P&S Eunice Brine St. BW-002 Cavern Pressure Test Looking NNE



Date: October 25, 1999 By: Wayne Price-OCD

P&S Eunice Brine St. BW-002 Cavern Pressure Test Looking NW



10-25-99 P45 BRINE EUNICE#1 Dischard # BW-002 Sec. 34 Township-21 RANGe 37 Time - 8:00 - 12:00 Am Open hole & CASING TESt Paul Prather ane Prother oco playe ver

Southwestern Instrument Zompany Clock - Meter and Gauge Repair Service

PHONE (505) 394 - 2377

EUNICE, NEW MEXICO 88231

P. O. BOX 1352

10=22=39

(MHOM TT HAY CO CELL:

We dered we certify fepairing and calibrating of tristol reductor $\theta{=}1000_{d}$ massure recorder for degerral fervice Co. on the above date.

Villiam S. Cottrell



A. PLS BRING EUNICE #1 B. CAVERN BW OOZ C. WAter Sec. 34-21 & 37E. D. NO PAOKER API# 30°25 26 884 E 11-15-02 Time 9: AM 11 PM F PAUL PRACHER Tame Phank oco Alan



÷-PHS BRINE (CNS/NG + FOTHINETIN) PHS BRINE (CNS/NG + FOTHINETIN) TEST WILD WATER With Letter "O" & P 2005 Ser 201 TO 18 P 2005 The second second Sec. 34 TWP 21 & R 37E Sec. 34 TWP 21 A LEA COUNTY CO. MAIN Lane Prochur W. Kien STAte MAIN AM AM





NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON Governor Jennifer A. Salisbury Cabinet Secretary Lori Wrotenbery Director Oil Conservation Division

PIS BW-02 CHAPARREL BW-25

October 20, 2001

<u>CERTIFIED MAIL</u> <u>RETURN RECEIPT NO.</u> 5357 7508

Attention: Brine Well Operators

Re: Mechanical Integrity Testing of Brine Supply Wells

The Underground Injection Control Program of the Federal Safe Drinking Water Act requires that operators demonstrate mechanical integrity of all injection wells by ensuring there are no leaks in the tubing, casing, or packer, and injected/produced fluids are confined within the piping and injection zones.

The Oil Conservation Division (OCD) requires operators of brine supply wells to perform the following mechanical integrity test:

- 1. At least once every five years isolate the cavern formation from the casing/tubing annuals and hydrostatic fluid pressure test the casing at 300 psig for 30 minutes. New brine wells and wells being worked over will have to be tested in this manner before operations begin.
- 2. Annually perform an open hole cavern formation pressure test by pressuring up the formation with fluids to one and one-half times the normal operating pressure or 300 psig whichever is greater for four hours. However, no operator may exceed surface injection or test pressures that may cause formation fracturing or system failures. Systems requiring test pressures less than 300 psig or methods that use testing media other than fluids, i.e. gas, must be approved by OCD prior to testing. Brine supply wells operating with isolation packers will have to pressure test both the cavern formation and casing/tubing annuals.

Please find enclosed an "OCD Brine Well Test Schedule November 2001" and "Brine Well Test Procedure Guidance Document" for this November 26 through November 30, 2001. Please have your well ready for testing on the date and time you are scheduled. Please refer to the Well Test Schedule attached for the <u>Type of Test</u> you are scheduled to perform. You must receive prior OCD approval to alter the scheduled time or type of test.

What's New!! Please note that operators are required to have their pressure recording devices calibrated to 500 psig and 8-hour clock. See Guidance Document attached.



NEW MEXICO ENERGY, MINERALS and TURAL RESOURCES DEPARTMENT

GARY E. JOHNSON Governor Jennifer A. Salisbury Cabinet Secretary Lori Wrotenbery Director Oil Conservation Division

PIS BW-02 CHAPARREL BW-25

October 20, 2001

<u>CERTIFIED MAIL</u> <u>RETURN RECEIPT NO.</u> 5357 フ508

Attention: Brine Well Operators

Re: Mechanical Integrity Testing of Brine Supply Wells

The Underground Injection Control Program of the Federal Safe Drinking Water Act requires that operators demonstrate mechanical integrity of all injection wells by ensuring there are no leaks in the tubing, casing, or packer, and injected/produced fluids are confined within the piping and injection zones.

The Oil Conservation Division (OCD) requires operators of brine supply wells to perform the following mechanical integrity test:

- 1. At least once every five years isolate the cavern formation from the casing/tubing annuals and hydrostatic fluid pressure test the casing at 300 psig for 30 minutes. New brine wells and wells being worked over will have to be tested in this manner before operations begin.
- 2. Annually perform an open hole cavern formation pressure test by pressuring up the formation with fluids to one and one-half times the normal operating pressure or 300 psig whichever is greater for four hours. However, no operator may exceed surface injection or test pressures that may cause formation fracturing or system failures. Systems requiring test pressures less than 300 psig or methods that use testing media other than fluids, i.e. gas, must be approved by OCD prior to testing. Brine supply wells operating with isolation packers will have to pressure test both the cavern formation and casing/tubing annuals.

Please find enclosed an "OCD Brine Well Test Schedule November 2001" and "Brine Well Test Procedure Guidance Document" for this November 26 through November 30, 2001. Please have your well ready for testing on the date and time you are scheduled. Please refer to the Well Test Schedule attached for the <u>Type of Test</u> you are scheduled to perform. You must receive prior OCD approval to alter the scheduled time or type of test.

What's New!! Please note that operators are required to have their pressure recording devices calibrated to 500 psig and 8-hour clock. See Guidance Document attached.

Brine Well Operators Oct 20, 2001 Page 2

<u>What's New!!</u> All operators will provide to the OCD the maximum test pressure that will not cause formation fracturing or system failures.

Operators will be responsible for providing equipment and shall bear all costs incurred. All tests must be witnessed by the New Mexico Oil Conservation Division. Operators failing to abide by the procedures, type of test, and time schedules listed herein may be required to shut-in their systems until OCD has an opportunity to approve and witness testing.

If you require any further information or assistance please do not hesitate to write or call me at 505-476-3487 or E-mail WPRICE@state.nm.us.

Sincerely Yours,

Wayne fin

Wayne Price- Senior Envr. Engr.. Environnemental Bureau

cc: OCD District Offices

Attachments-1.OCD Brine Well Test Schedule November 20012.Brine Well Testing Procedure Guidance Document

Brine Well Testing Procedure Guidance Document

- The cavern and all piping must be filled, pressured up and stabilized for a period of at least 24 hours prior to testing. If this test requires a packer then casing/tubing annulus must be loaded with inert fluid 24 hours prior to testing.
- 2) Have manpower and equipment available for pressure test. Wellhead shall be prepared for test and all valves and gauges should be in good working order.
- 3) Pumps, tanks, external lines etc. must be isolated from the wellhead during test.
- 4) A continuous recording pressure device with an 8-hour clock (min) shall be installed on the casing/tubing annulus. The pressure range shall not be greater than 500 psig. The operator must provide proof that the pressure-recording device has been calibrated within the past 6 months. Note: Wells with packer installed: If this test requires both the casing/tubing annulus and cavern to be tested then two recording devices must be supplied or one recording device with two pins.
- 5) A minimum of one pressure gauge shall be installed on the casing/tubing annulus.
- 6) OCD must witness the beginning of test (putting chart on) and ending of test (removing chart). At the end of test operator may be required to bleed-off well pressure to demonstrate recorder and gauge response.
- 7) The Operator will supply the following information on the pressure chart:
 - A. Company Name, Well Name, API #, Legal Location.
 - B. Test Procedure (1) Casing + Formation (2) Casing Test Only (3) Both (4) Other
 - C. Testing Media: Water, Gas, Oil, Etc.
 - D. Date, time started and ending.
 - E. Name (printed) and signature of company representative and OCD Inspector
- 8) <u>TEST ACCEPTANCE</u>: The OCD will use the following criteria in determining if a well has passed the Mechanical Integrity Test:
 - A. <u>Passes</u> if Zero Bleed-Off during the test.
 - B. <u>Passes</u> if Final Test Pressure is within $\pm 1\%$ of Starting Pressure, if approved by the OCD inspector.
 - C. <u>Fails</u> if any Final Test Pressure is greater than $\pm 1\%$ of Starting Pressure. Operators must investigate for leaks and demonstrate that mechanical integrity of the well(s) by ensuring there are no leaks in the tubing, casing, or packer, and injected/produced fluids are confined within the piping and injection zones. Wells shall not resume operations until approved by OCD.
- Note: OCD recognizes that different operations, well designs, formation characteristics and field conditions may cause variations in the above procedures. If operator wishes to make or anticipate changes please notify the OCD for approval. All operators are responsible to notify OCD of any procedure that may cause harm to the well system or formation. Please be advised that OCD approval does not relieve any operator of liability should operations result in pollution of surface water, groundwater, or the environment.

OCD BRINE WELL TESTING S	CHEDULE 2001				CD Contact W	ayne Price ce	1 505-660-1067			
Company	0P#	· Facility Name	╂╍╂ ┨╺┨	Date of Test	Start	Stpp	Type of Test(8) Requi	hed Contact Person	Telephone	FAX #/cell
Stearns Inc.	BW-013	Crossroads Area Crossroads	w	28-Nov-01	12 noon	4:00 PM	2 Pressure test cavem	L.A. Steams	1-505-675-2356	1-505-675-2339
Marbob Brine Well Jims Water Ser.	BW-005 BW-005	Loco Hills Area M. Dodd "A" BW#1 SE of Artesia	P P	27-Nov 27-Nov	8:00 AM 10:00 AM	1:00 PM 2:00 PM	2 Pressure test cavem Pressure test cavem or c 1.2 or 3	Doyle Davis Boyle Davis Sammy Stoneman	748-5975 cell 1 1-505-748-1352	1-505-748-2523 1-505-748-3227
Key Energy Sourdoork-Decemican	BW-018	Hobbs Area Truckers #2 (Hobbs) Lobbe Stellor	Wen	28-Nov-01	8:00 AM	12 noon 1-00 BM	2 Pressure test cavem	Rayce Crowell Dishord Loots	(505) 383-9171 505 383-9171	505-910-4185 207 2000
Zia Transportation Marathon Brine St	BW-018 BW-015	Safty Dog-Ark Jct Marathon Road	Men Wen	28-Nov-01 28-Nov-01	10:00 AM	2:00 PM 3:30 PM	 Pressure test cavern Pressure test cavern Pressure Test Casing 	Piter Bergstein CW Trainer	808-741-1080	0060-760
P&S Brine	BW-002	Eunice Area Eunice Brine Station		28-Nov-01	8:00 AM	12 1000	2 Pressure test cavern	Dick Prather	505-394-2545	304-2428
Key Simms-McCastand Yale E. Key (Old Goldstar)	BW-009A BW-028	Eunice Brine Station Eunice Brine Station	Į	28-Nov-01 28-Nov-01	9:00 AM 10:00 AM	1:00 PM 2:00 PM	2 Pressure test cavern 2 Pressure test cavern	Royce Crowell Royce Crowell	(505) 393-9171 1-505-394-2504	505-910-4185 1-505-394-2560
		Cartsbad Area								
I& W Key Energy-Carisbad	BW-06 BW-019	Carlsbad -Euginie Rowland Truckers	포포	30-Nov-01 30-Nov-01	8:00 AM 9:00 AM	12 noon 1:00 PM	2 Pressure test cavem 2 Pressure test cavem	George Parchman John Hutcheson	1 505-885-8683 1-505-885-2053	885-8477 cell 390-1833
Scurlock/Permian	BW-027 &27A	Carlsbad Brine St.	Fri	30-Nov-01	10:00 AM	2:00 PM	2 Pressure test cavern	Richard Lentz	505-392-8212	392-6988
		Wells Already Tested I	- 1002 - 1002							
Gandy Gandy	BW-04 BW-22	Wasserfrund-Edison Tatum Brine St.								
Ray Westall	LZ-MB	Loco Hills Brine St.	-++ -++							
Chaparral SWD	BW-25	weils being Kepaired- Salado Brine #2- Jai								
Notes:										
Type of Pressure Test:	1 Casing Test			Isolate cavern formation	from the casin	p/tubing annuals	s and hydrostatic fluid pressu	re test the casing at 300 psi	ig for 30 minutes.	
	2 Open Hole Cav	vem Pressure Test		Open hole cavern formi 300 psig whichever is g OCD prior to test shall t	atton pressure to reater for four h approve test pre	est by pressurin ours. Operator: issures below 3	g up the formation with fluid t s shall not exceed surface pre 00 psig and methods that use	o one and one-half times th issures that may cause forn media other than fluids.	e normal operating pre nation fracturing or sys	assure of tem failures.
				Brine supply wells oper	ating with pack	ers will have to p	pressure both the cavern form	lation and casing/fubing an	nuais.	
-	3 Others			Nitrogen-Brine Interface	e Test, Nitroger	Test, Etc.				
			1							

ŝ

....



11-16-2000 P+S BRINE EUNICE#, DischARG BW-002 Time 9Am 1:15 Pm open hole CASING Test Paul Prate OCALL 11-16-00-DAte

÷



Price, Wayne

From:	Sharp, Karen
Sent:	Thursday, November 16, 2000 3:01 PM
To:	Price, Wayne
Cc:	Williams, Chris
Subject:	P&S Brine Sales

As a follow-up to my phone call to you this afternoon, please be advised of the following: E.L. Gonzales witnessed a 4-hour wellbore test today, Nov 16 00, on the Eunice #1, O-34-21S-37E, for P & S Brine Sales. Test began @ 9:00 a.m. @ 440#. Had good build up. Ending time was 1:15 p.m. @ 440#. Had good bleed off. No pkr; is open-ended. He noted that the well is properly marked and location looks good. Mr. Dink Prather has the original chart for the well. He indicated he would send the original chart to Santa Fe and copies to Hobbs office and one for his files. If you need to contact Mr. Prather, his cell phone is 390-1437. Please note: This well is not located in RBDMS; therefore, data has not been entered into any record.



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

5051 4454 BW-002 P+5 BW-025 <5I

GARY E. JOHNSON Governor Jennifer A. Salisbury Cabinet Secretary

Lori Wrotenbery Director Oil Conservation Division

October 20, 2000

<u>CERTIFIED MAIL</u> <u>RETURN RECEIPT NO.</u>

Attention: Brine Well Operators

Re: Mechanical Integrity Testing of Brine Supply Wells

The Underground Injection Control Program of the Federal Safe Drinking Water Act requires that operators demonstrate mechanical integrity of all injection wells by ensuring there are no leaks in the tubing, casing, or packer, and injected/produced fluids are confined within the piping and injection zones.

The Oil Conservation Division (OCD) requires operators of brine supply wells to perform the following mechanical integrity tests:

- 1. At least once every five years isolate the cavern formation from the casing/tubing annuals and hydrostatic fluid pressure test the casing at 300 psig for 30 minutes. New brine wells and wells being worked over will have to be tested in this manner before operations begin.
- 2. Annually perform an open hole cavern formation pressure test by pressuring up the formation with fluid to one and one-half times the normal operating pressure or 300 psig whichever is greater for four hours. Operators shall not exceed surface pressures that may cause formation fracturing or system failures. OCD prior to test shall approve test pressures below 300 psig and methods that use media other than fluids. Brine supply wells operating with packers will have to pressure both the cavern formation and casing/tubing annuals.

Please find enclosed an "OCD Brine Well Test Schedule December 2000" and "Brine Well Test Procedure Guidance Document" for this December 8th through 18th 2000. Please have your well ready for testing on the date and time you are scheduled. Please refer to the Well Test Schedule attached for the <u>type of test</u> you are scheduled to perform. You must receive prior OCD approval to alter the scheduled time or type of test. Brine Well Operators 10/20/00 Page 2

Operators will be responsible for providing equipment and shall bear all costs incurred. All tests must be witnessed by the New Mexico Oil Conservation Division. Operators failing to abide by the procedures, type of test, and time schedules listed herein may be required to shut-in their systems until OCD has an opportunity to approve and witness testing.

If you require any further information or assistance please do not hesitate to write or call me at (505-827-7155).

Sincerely Yours,

Warpe Pine

Wayne Price-Pet. Engr. Spec. Environmental Bureau

cc: OCD District Offices

Attachments- 1. OCD Brine Well Test Schedule December 2000. 2. Brine Well Testing Procedure Guidance Document.

of 200(
December
SCHEDULE
ELL TEST
BRINE WE
OCD

Company	#d0	Facility Name	Date of Test	Start	Stop	Type of Test(s) Required	Contact Person	Telephone	FAX #
Marbob Brine Well	BW-029	M. Dodd "A" BW#1	December 08, 2000	1:00 PM	5:00 PM	2 Pressure test cavern	Doyle Davis Raye Miller	748-5975 cell 1 748-3303	-505-746-2523
P&S Brine Simms-McCasland Saily Dog, Inc.	BW-002 BW-009A BW-008	Eunice Eunice Water ST. Eunice Brine Station Arkansas-Jct	December 11, 2000 December 11, 2000 December 11, 2000	8 am 9:30 am 11 am	12 noon 1:30 pm 3 pm	 Pressure test cavern Pressure test cavern Pressure test cavern 	Paul Prather Bob Patterson Mr. Piter Bergstein Walter Brisco	1-505-394-2545 1-505-394-2581 1-806-741-1080	1-505-394-2426 1-505-394-2584
Stearms Inc. Gandy Corp. Key Energy	BW-013 BW-022 BW-018	Crossroads Tatum Water St. Truckers #2 (Hobbs)	December 12, 2000 December 12, 2000 December 12, 2000	8:00 AM 9:00 AM 10:30 AM	12 noon 1:00 PM 2:30 PM	 Pressure test cavern Pressure test cavern Pressure test cavern 	L.A. Steams Larry Gandy Pete Tumer	1-505-675-2356 1-505-398-4960 1-505-397-4994	1-505-675-2339 cell 369-5721 1-505-393-9023
I&W Trucking Loco Hills Brine	BW-006 &6A BW-021	Carisbad Yard Loco Hills	December 13, 2000 December 13, 2000	8:00 AM 1:30 PM	12 noon 5:30 PM	2 Pressure test cavern 2 Pressure test cavern C	George Parchman D. Matoney or R. Harris	1-505-885-6663 1-505-677-2370	1-505-885-8477 1-505-677-2361
Goldstar Quality Oil (Salado Brine Sales)	BW-028 BW-025	Eunice Brine Station Salado Brine St. #2	December 14, 2000 December 14, 2000	9:30 am 11am	1:30 pm 3 pm	2 Pressure test cavem 2 Pressure test cavem	Royce Crowell see P&S	1-505-394-2504	1-505-394-2560
Key Energy-Carlsbad Scurlock/Permian Jims Water Ser.	BW-019 BW-027 &27A BW-005	Rowland Truckers Carlsbad Brine St. SE of Artesia	December 15, 2000 December 15, 2000 December 15, 2000	8:00 AM 9:00 AM 10:30 AM	12 noon 1:00 PM 2:30 PM	 Pressure test cavern Pressure test cavern Pressure test cavern 	John Hutcheson Jim Ephraim Sammy Stoneman	1-713-672-8092 1-505-748-1352	-505-887-3011 1-713-672-7609 1-505-746-3227
Scurtock-Permian Gandy- WasserHaun	BW-012 BW-004	Hobbs Station Buckeye St.	December 18, 2000 December 18, 2000	8:00 AM 9:00 AM	12 noon 1:00 PM	2 Pressure test cavern 2 Pressure test cavern	Richard Lentz Larry Gandy	1-505-392-8212 1-505-398-4960	1-505-392-6988 cell 369-5721
Notes:									
Type of Pressure Test:	1 Casing Test		Isolate cavern formation	l from the casin	g/tubing annua	als and hydrostatic fluid pressure te	est the casing at 300 psig	g for 30 minutes.	
	2 Open Hole Cave	m Pressure Test	Open hole cavern form: 300 psig whichever is g OCD prior to test shall a Brine supply wells oper	ation pressure to reater for four h pprove test pre ating with packe	st by pressuri ours. Operato ssures below i irs will have to	ng up the formation with fluid to on rs shall not exceed surface pressu 300 psig and methods that use me pressure both the cavern formatio	e and one-half times the res that may cause form dia other than fluids. n and casing/tubing ann	normal operating f ation fracturing or s uals.	ressure or ystem failures.

-

ļ

7

*

Nitrogen-Brine Interface Test, Nitrogen Test, Etc.

3 Others

-

Brine Well Testing Procedure Guidance Document

- 1) The cavern and all piping must be filled, pressured up and stabilized for a period of at least 24 hours prior to testing. If this test requires or utilizes a packer then the casing/tubing annulus must be loaded with inert fluid 24 hours prior to testing.
- 2) Have manpower and equipment available for pressure test. Well head shall be prepared for test and all valves and gauges should be in good working order.
- 3) Pressure devices i.e pumps, truck pumps, etc. must be isolated from the well head during test.
- 4) A continuous recording pressure chart with an 8 hour clock shall be installed on the casing/tubing annulus, as directed by the OCD, with a pressure range of not greater than 500 psig. The operator must provide proof that pressure recording device has a range of 0-500 psig and has been calibrated within the past 6 months. Wells, with isolation packers installed, which requires both the casing/tubing annulus and cavern to be tested will require two recording devices or one recording device with two pins. Operators may utilize other types of pressure recording devices, such as electronic data loggers, etc., if approved by OCD.
- 5) A minimum of one pressure gage shall be installed in the system as directed by OCD.
- 6) OCD must witness the beginning of test (putting chart on) and ending of test (removing chart). At the end of test operator may be required to bleed-off pressure to demonstrate recorder response.
- 7) The Operator will supply the following information on the pressure chart before starting test:
 - 1. Company name, discharge plan #, well name and number, legal location UL, section, township, range and county.
 - 2. Type of Test: Open Hole, Casing Test, or Both.
 - 3. Date, time test started, time stop.
 - 4. Chart and Recorder information. (can be attached)
 - 5. Normal operating surface and formation fracture pressure. (can be attached)
 - 6. After Test Completed:

Name (printed) and signature of company representative and OCD inspector.

Note: NMOCD recognizes that different operations, well constructions, well designs and field conditions may cause variations in the above procedures. Operator is responsible to notify OCD of any procedure that may cause harm to the well or formation. If operator wishes to make or anticipate changes you must notify the OCD for approval.

OCD December of 2000 Brine Well Testing



10-5-04 PLS Brine Eunice #1 Unit Letter O Sec 24 TWP215A37E Lea County fi' have 280th CO-Georse Locke Stote Man B. H=



STATE OF NEW MEXICO TO: Dave Bayer '90 JAN 17 AM 9 SPATE: 1/12/20 FROM: John Parker SUBJECT: P&S Brine Sales Financial Assurance The attached memo from Gini Nelson raises some issues which require input from OCD. EID would like to comply with PES's request to terminate the trust agreement and there by get "Dink" off our backs. Perhaps you could meet with EID staff and Ms. Nelson next work to expedite this process.

ADM 031A Issued 6/78