

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

CONFIDENTIAL

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	

API #30-003-20015

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
LH 3074	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
SHELL WESTERN E&P INC.		SWEPI ET AL STATE
3. Address of Operator		9. Well No.
P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)		1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>F</u> <u>1605</u> FEET FROM THE <u>NORTH</u> LINE AND <u>1624</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>2</u> TOWNSHIP <u>4S</u> RANGE <u>13W</u> NMPM.		WILDCAT
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
7650' GL		CATRON

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	DST & SWAB TSTD ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

8-05-87: Ran DST #1.

4-11-91
location OK
REG

8-20-87: Spot three 100' CIs "H" cmt plugs w/tops @ 6897', 5953' & 5110'.

8-21 to 8-23-87: Perf'd from 4834' - 4870' (4 JSPF). Ran DST #2. Pmpd CIs "H" cmt (volume unknown) from 5110' to 4793'.

8-25-87: Set BP @ 4280'.

8-26 to 8-28-87: Perf'd 4180' - 4200' (2 JSPF). Acd perfs 4180' - 4200' w/924 gals 15% HCl. Swab tstd well. Set cmt ret @ 4165'.

8-29 to 9-01-87: Sqzd perfs 4180' - 4200' w/35 sx CIs "H" cmt. Perf'd 4073' - 4130' (2 JSPF). Acd perfs 4073' - 4130' w/3780 gals 15% HCl. Swab tstd well.

9-02 to 9-03-87: Set cmt ret @ 4060'. Sqzd perfs 4073' - 4130' w/35 sx CIs "H" cmt. Perf'd 4022' - 4034' (JSPF). Acd perfs 4022' - 4034' w/504 gals 15% HCl. Swab tstd well. Set cmt ret @ 3995'. Sqzd perfs 4022' - 4034' w/35 sx CIs "H" cmt. Dmpd 30' cmt on top of ret.

(CONTINUED OF REVERSE SIDE)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. Fore A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE SEPTEMBER 21, 1987

APPROVED BY R. E. Johnson TITLE DATE 1-7-88

9-04-87: Spotted 100' cmt (Cl's "H") plug from 1050' to 950'. Spotted 50' cmt plug @ surf.
Cut off csg's 3' below GL. Installed P&A marker.