

2-1
Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-007-200
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>7. Lease Name or Unit Agreement Name Vermejo Park 3117</p>	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Coal Methane	8. Well No. 012-I		
2. Name of Operator Pennzoil Exploration & Production Company	9. Pool name or Wildcat Wildcat		
3. Address of Operator P.O. box 2967, Houston, TX 77252	4. Well Location Unit Letter <u>I</u> : <u>1883</u> Feet From The <u>South</u> Line and <u>668</u> Feet From The <u>East</u> Line Section <u>01</u> Township <u>31N</u> Range <u>17E</u> NMPM <u>Colfax</u> County		
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 8111 GR			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/15/91 Estimated start of work.

1. Remove surface equipment. Pull tubing.
2. Clean out to 1400'. Place 27 sks (110') plug from 60' below to 50' inside casing w/class A @ 15.6 ppg. Fill to surface w/gel mud.
3. Place 13 sks (50') surface plug w/class a @ 15.6 ppg.
4. Place well marker, remove junk and debris from location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. D. Williamson TITLE Operations Superintendent DATE 8/15/91

TYPE OR PRINT NAME L. D. Williamson TELEPHONE NO. 376/2817

(This space for State Use)

APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 8-29-91

CONDITIONS OF APPROVAL, IF ANY