

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.
30-007-20153
5. Indicate Type of Lease
STATE ☐ FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other Coal Bed Methane

2. Name of Operator
El Paso Energy Raton, LLC

3. Address of Operator
P O Box 190 Raton N.M. 87740

4. Well Location

Unit Letter J : 1566 feet from the South line and 1808 feet from the East line

Section 31 Township 30N Range 19E NMPM Colfax County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
7935'(GR)

7. Lease Name or Unit Agreement Name:
VPR B

8. Well No. 9

9. Pool name or Wildcat

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: Commingle Raton coals with the Vermejo coals ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. POOH with rods and tubing
2. Perforate 1720-24, 1704-07, 1672-74, 1661-64, all 4spf
3. Stimulate perforations with N2 foam frac. (Frac details to be decided)
4. Perforate 1580-83, 1566-68, all 4spf
5. Stimulate perforations with N2 foam frac (Frac details to be decided)
6. Perforate 1020-23, 1016-18, 985-88, 935-38, 932-34, all 4spf
7. Stimulate perforations with N2 foam frac. (Frac details to be decided)
8. Clean out well to TD
9. RIH with tubing and rods. Return to production

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Potter TITLE Completion Consultant DATE 12-18-00

Type or print name Mike Potter

Telephone No. 505 445 4685

(This space for State use)

APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 12/22/00

Conditions of approval, if any: