

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.
30-007-20157

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:
VPR B

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other Coal Bed Methane

2. Name of Operator
El Paso Energy Raton, LLC

8. Well No. 20

3. Address of Operator
P O Box 190 Raton, NM 87740

9. Pool name or Wildcat

4. Well Location

Unit Letter N : 1075 feet from the South line and 1413 feet from the West line

Section 25 Township 30N Range 18E NMPM Colfax County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
8166' (GR)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: Commingle Raton Coals with the Vermejo Coals ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. POOH with Rods and Tubing
2. Perforate 1894-96, 1838-43, 1828-35, all 4spf
3. Stimulate perforations with N2 foam frac. (Frac details to be decided)
4. Perforate 1468-70, 1410-14, 1404-07, all 4spf
5. Stimulate perforations with N2 foam frac. (Frac details to be decided)
6. Perforate 1210-18, 1188-96, 1177-80, 1143-47, all 4spf
7. Stimulate perforations with N2 foam frac. (Frac details to be decided)
8. Perforate 1083-87, 1028-32, 1016-20, 956-60, all 4spf
9. Stimulate perforations with N2 foam frac. (Frac details to be decided)
10. Perforate 852-59, 796-804, 759-63, 736-38, all 4spf
11. Stimulate perforations with N2 foam frac. (Frac details to be decided)
12. Clean out well to TD.
13. RIH with tubing and rods. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Potter TITLE Completion Consultant DATE 12-18-00

Type or print name Mike Potter Telephone No. 505 445 4685

(This space for State use)

APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 12/22/00
Conditions of approval, if any: