

NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Consolidated Minerals Development Corporation
110 South Second St. (Address) Raton, New Mexico
LEASE Sarah "S" WELL NO. 1 UNIT J S 26 T 31 N R 23 E
DATE WORK PERFORMED 9/10/56 POOL Wildcat (Colfax)

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off
☒ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

9/10/56 Began Cable Tool Hole

9/11/56 Set 20' of 10" I. D. Second hand surface casing, cemented w/3 sax cement, dumped down outside to surface.

9/13/56 Drilled cement plug.

*Bill Hoar - Trans American Inc
295-4649 Raton*

*Quad 10
On W. side of Raton*

445-9636

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____	_____	_____

ILLEGIBLE

OIL CONSERVATION COMMISSION

P. O. BOX 871

SANTA FE, NEW MEXICO

June 25, 1959

C
O
P
Y
American Surety Company
420 Denver National Building
821 17th Street
Denver 2, Colorado

ATTENTION: Mr. G. G. Haller

Re: 11-561-192 Consolidated
Minerals Development Corp.
\$5,000 One Well Bond NW/4
SE/4 Section 26, Township
31 North, Range 23 East,
Colfax County, New Mexico.

Gentlemen:

Our records reflect that the subject well has not been properly plugged and abandoned. We have had considerable correspondence with a Mr. F. R. Calley, 150 Broadway, New York 38, New York, in an attempt to get this well plugged. To date our efforts have not been successful. It is now our intent to inspect the subject well and to proceed with the steps necessary to force-plug it.

If you have any questions concerning this matter, do not hesitate to call upon me.

Very truly yours,

R. L. STAMETS
Geologist

RLS/pj