

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.  
N/A

7. Lease Name or Unit Agreement Name  
T-4 (Enhanced Recovery)  
Unit

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
Enercap Corporation

8. Well No.  
6 (Jeanie #6)

3. Address of Operator  
16945 Northchase, Ste. 1700 Houston, TX 77060

9. Pool name or Wildcat  
Wildcat

4. Well Location  
Unit Letter C : 965 Feet From The N Line and 2145 Feet From The W Line  
Section 17 Township 11 N Range 26 E NMPM Guadalupe County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
4,753.0

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull rods, pump and tubing. Run open ended tubing to 714 ft. Equalize 15.5 # cement to a minimum depth of 650 ft. Fill remainder of hole with water. Pull tubing to surface. Set 20 ft. surface plug. Set dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ramon Elias TITLE V. P. Operations DATE 6/3/92  
(713)  
TYPE OR PRINT NAME Ramon Elias TELEPHONE NO. 876-0170

(This space for State Use)  
APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 6-8-92  
CONDITIONS OF APPROVAL, IF ANY: