

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY GENERAL CRUDE OIL COMPANY 314 Commerce Building, Abilene, Texas
(Address)

LEASE James H. Simpson WELL NO. 1 UNIT B S 21 T-10-8 R-23-E
DATE WORK PERFORMED July 31, 1955 POOL Wildcat

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☒ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

1. Circulated open hole with drilling mud; weight-9.8 #/gal.
2. Set 35 sack cement plug from 3030 to 2970 feet by displacement from drill pipe.
3. Set 20 sack cement plug from 110 to 15 feet by displacement from drill pipe.
4. Set 4" steel pipe marker on top of the surface pipe.
5. Casing left in the well: 36 feet, 13" OD, 40 # surface pipe; 3070 feet 8-5/8" 28# intermediate casing.

Note: Pits will be filled and location levelled and cleaned up after pits have dried and the rig has been moved off.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____	_____	_____

(Company)

OIL CONSERVATION COMMISSION

Name R. L. Stant
Title Geologist
Date July 27, 1955

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name F. A. Hunter F. A. HUNTER
Position District Production Superintendent
Company General Crude Oil Company

April 2, 1956: Pits have been filled and the location levelled and cleaned up. The marker for a dry hole location has been installed.

F. A. Hunter