

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
Fee

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator McClellan Oil Corporation	8. Farm or Lease Name Burner Fee
3. Address of Operator P.O. Drawer 730, Roswell, NM 88202	9. Well No. 2
4. Location of Well UNIT LETTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM East LINE, SECTION 31 TOWNSHIP 11-N RANGE 22-E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4854' G.L.	12. County Guadalupe

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

OTHER Temporarily shut-in, waiting on comp.

PLUG AND ABANDON

CHANGE PLANS

SUBSEQUENT REPORT OF:

REMEDIAL WORK

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOBS

OTHER

ALTERING CASING

PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/13/84: Drill out D.V. Tool. Circulate hole with 2% KCL.
 8/14/84: Ran cement bond log. Perf 5573'-5576', 8 holes. Broke down 1500 psi.
 8/15/84: Acidized with Halliburton 1000 gals. 15% MCA acid. Swab back load (No gas or oil.)
 8/16/84: Set CIBP at 5555' and tested 2000 psi. Perf at 5528'-5530, 6 holes. Broke formation at 1900 psi. Swabbed well dry.
 8/17/84: Acidized with 750 gals. 10% Morrow Flow BC & 1000 SCF/bbl nitrogen.
 8/20/84: Flowed and swabbed back load. (No gas or oil.)
 8/21/84: Set CIBP at 5510'. Perf 5477'-5482', 12 holes. Swabbed zone, no show.
 8/22/84: Acidized zone with 400 gals. 10% MSA-acid. Broke down at 2000 psi. Swab back load (show of gas) would not flow.
 8/23/84: Acidized zone with 1500 gal. 15% MSA/1000 SCF/bbl N₂. Flowed and swabbed well.
 8/24/84: Flowed well down slight show of gas.
 8/26/84: Swabbing well.
 8/27/84: Frac zone with 15000 gal pure gel & 20% CO₂. Average rate 12 bbls/min.
 8/28/84: Flowing frac load back. Swabbing well until 8/31/84.
 8/31/84: Frac zone 14000 gals pure gel & 67 tons CO₂, 15000# 20/40 sand, 8000# 20/40 Interprops. Flowing loads back.
 9/1/84 - 9/9/84: Swabbing load back. Slight show of gas.
 9/9/84: Ran BHP bomb. 2127 psi after 72 hours. (Continued on next page)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mitch Lee TITLE Production Engineer DATE 10/24/84

APPROVED BY [Signature] TITLE DR DATE 10-29-84

CONDITIONS OF APPROVAL, IF ANY:

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	✓

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
Fee

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER-

2. Name of Operator
McClellan Oil Corporation

3. Address of Operator
P.O. Drawer 730, Roswell, NM 88202

4. Location of Well
UNIT LETTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM
THE East LINE, SECTION 31 TOWNSHIP 11-N RANGE 22-E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
Burner Fee

9. Well No.
2

10. Field and Pool, or Wildcat
Wildcat

15. Elevation (Show whether DF, RT, GR, etc.)
4854' G.L.

12. County
Guadalupe

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING

TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT

PULL OR ALTER CASING OTHER Temporarily shut-in, waiting on completion CASING TEST AND CEMENT JOB OTHER

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/11/84: Set CIBP at 5450'. Perf 5394'-5396', 8 holes. Acidized with 500 gal 7-1/2 NEFE acid.

9/12/84: Swab back load (show of gas). Swabbing gas and formation H₂O.

9/14/84: Run RBP to 5280'. Perf 5260'-5268', 18 holes. Acidized with 2000 gal 7-1/2% NEFE acid.

9/17/84: Set CIBP at 5350'. Dumped 20' of cement on top.

9/19/84: Frac well using 16000 gal pure gel 40, 8000 gal CO₂, 15000# 20/40 sand, 6000# 20/40 interprops.

9/20/84: Flowing good gas but making lots of salt water. Swab well. Still good show of gas.

10/11/84: Tubing psi - 1600. Casing psi - 1500 psi.

10/19/84: Set CIBP at 5020'. Perf 4558'-4635', 19 holes. Acidize zone with 3000 gal 10% NEFE acid.

10/20/84 - 10/23/84: Swabbed on well. No show of gas.

10/24/84: Shut in well, waiting on further completion.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mitch Lee TITLE Prod. Eng. DATE 10/24/84

APPROVED BY [Signature] TITLE MEMBER DATE 10-29-84

CONDITIONS OF APPROVAL, IF ANY: