

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ CO ₂ OTHER-		7. Unit Agreement Name
2. Name of Operator Amoco Production Co.		8. Farm or Lease Name Heimann
3. Address of Operator P. O. Box 68 - Hobbs, NM 88240		9. Well No. 3
4. Location of Well UNIT LETTER <u>K</u> , <u>1830</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>34</u> TOWNSHIP <u>21-N</u> RANGE <u>33-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Und. Tubb
15. Elevation (Show whether DF, RT, GR, etc.) 5068 GR		12. County Harding

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER <u>Squeeze Production Casing</u> ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to squeeze behind 4 1/2" casing per the following procedure:

Kill well and pull tubing. Set a cast iron bridge plug at 2000'. Run pipe recovery log to determine top of cement. Perforate 4 1/2" casing with 4 JSPF approx. 20' above top of cement. Establish circulation to check perfs. Run tubing and retainer. Set cement retainer 50' above perfs. Pump calculated amount of Western Lite Cement and 50 sx Class C Cement. Will use 110% of open hole volume for calculation. Pull tubing and wait on cement. Drill out cement retainer and cement.

0 + 2 NMOCD SF 1-Hou 1-Susp 1-LBG

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bob Davis TITLE Admin. Analyst DATE 9-2-80

APPROVED BY Carl Illing TITLE SENIOR PETROLEUM GEOLOGIST DATE 9/3/80
CONDITIONS OF APPROVAL, IF ANY: