

### OIL CONSERVATION DIVISION

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

P.O. Box 2088

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

DISTRICT III

00 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.  
30-021-20138

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.

#### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name  
BRAVO DOME CO2 GAS UNIT

Type of Well  
OIL WELL  GAS WELL  OTHER CO2

8. Well No.  
2033-301G

Name of Operator  
AMOCO PRODUCTION COMPANY

9. Pool name or Wildcat  
BRAVO DOME CO2 GAS UNIT

Address of Operator  
P.O. Box 303, AMISTAD, NEW MEXICO 88410

Well Location  
Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line  
Section 30 Township 20N Range 33E NMPM Harding County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
5090 GR

#### Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

##### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK   
TEMPORARILY ABANDON   
WELL OR ALTER CASING   
OTHER:   
PLUG AND ABANDON   
CHANGE PLANS

##### SUBSEQUENT REPORT OF:

REMEDIAL WORK   
COMMENCE DRILLING OPNS.   
CASING TEST AND CEMENT JOB   
OTHER:   
ALTERING CASING   
PLUG AND ABANDONMENT

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  
SEE RULE 1103.

MIRUSU, kill well as necessary, NUBOP, release packer, lay down production tubing and packer, run workstring to 2,560 feet, spot 10 sacks of class C cement, pull workstring, WOC, run workstring, tag cement, cement should be above 2,482 feet, pressure test casing to 500 psi, displace casing with corrosion inhibited fluid, pull workstring to 2,120 feet, spot 10 sacks of cement, pull workstring to 30 feet and fill casing with cement, NDBOP, RDMOSU, cut off wellhead, install PXA marker, cut off well anchors and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

NATURE D. Holcomb TITLE Field Foreman DATE 2-29-00  
NAME OR PRINT NAME Danny J. Holcomb TELEPHONE NO. (505) 374-3010

APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 3/9/00  
CONDITIONS OF APPROVAL, IF ANY