

## DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

## DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

## DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

## WELL API NO.

30-021-20182

## 5. Indicate Type of Lease

STATE ☐FEE ☐

## 6. State Oil &amp; Gas Lease No.

## 7. Lease Name or Unit Agreement Name

BRAVO DOME CO2 GAS UNIT

## 8. Well No.

1933-041G

## 9. Pool name or Wildcat

BRAVO DOME CO2 GAS UNIT

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

## 1. Type of Well

OIL  
WELL ☐GAS  
WELL ☐

OTHER

CO2

## 2. Name of Operator

AMOCO PRODUCTION COMPANY

## 3. Address of Operator

P.O. Box 303, AMISTAD, NEW MEXICO 88410

## 4. Well Location

Unit Letter G 1650 Feet From The North Line and 1650 Feet From The East Line  
Section 4 Township 19N Range 33E NMPM Harding County10. Elevation (Show whether DE, RKB, RT, GR, etc.)  
4970 GR

## 11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐CHANGE PLANS ☐PULL OR ALTER CASING ☐OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐PLUG AND ABANDONMENT ☒CASING TEST AND CEMENT JOB ☐OTHER: ☐

## 12 Describe Proposed or Completed Operations

(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

SEE RULE 1103

10/25/99

MIRUSU, kill well with fresh water, NUBOP, release packer, lay down 3 1/2" production tubing and packer, run 2 3/8" workstring to 2,480 feet, spot 45 sacks of Class C cement, pull workstring uphole and SDON.

10/26/99

Run workstring, tag cement at 2275. pressure test casing to 500 psi, ok. Displace casing with fresh water and corrosion inhibitor, pull workstring to 1,992 feet, spot 20 sacks of cement from 1992' - 1876', pull workstring to 30 feet, spot 5 sacks of cement from 30' - 3', NDBOP, cut off wellhead, install PXA marker, RDMOSU, cut off well anchors and clean location.

2/8/00 OK REG

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE DJ Holcomb TITLE Field Foreman DATE 11-4-99TYPE OR PRINT NAME Danny J. Holcomb TELEPHONE NO. (505) 374-3010

(This space for State Use)

APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 2/10/00

CONDITIONS OF APPROVAL, IF ANY