

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals, and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

**WELL API NO.**

30-021-20186

**5. Indicate Type of Lease**

STATE ☐

FEE ☐

**6. State Oil & Gas Lease No.**

**7. Lease Name or Unit Agreement Name**

BRAVO DOME CO2 GAS UNIT

**8. Well No.**

1833-011G

**9. Pool name or Wildcat**

BRAVO DOME CO2 GAS UNIT

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A

DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"

(FORM C-101) FOR SUCH PROPOSALS.)

**1. Type of Well**

OIL WELL ☐

GAS  
WELL ☐

OTHER

CO2

**2. Name of Operator**

AMOCO PRODUCTION COMPANY

**3. Address of Operator**

P.O. Box 303, AMISTAD, NEW MEXICO 88410

**4. Well Location**

Unit Letter G : 1650 Feet From The NORTH Line and 1650 Feet From The EAST Line  
Section 1 Township 18N Range 33E NMPM HARDING County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
4815 GL

**Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

WELL OR ALTER CASING ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

**2. Describe Proposed or Completed Operations**  
SEE RULE 1103.

(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

MIRUSU, Kill well as necessary, NUBOP, Rel pkr, LD production tbg and packer, Run tbg to 2500 ft, Spot 35 sx cmt, Pull tbg, WOC, Run tbg tag cmt, Cmt should be above 2470 ft, Prs tst csg to 500psi, disp well with mud laden fluid, Pull tbg to 2015 ft, Spot 17sx cmt, Pull tbg to 30 ft and fill csg with cement, NDBOP, Cut off wellhead, Install PXA marker, RD MOSU, Cut off SU anchors and clean location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

NATURE Billy E. Prichard TITLE Operations Specialist

DATE 1/20/98

OR PRINT NAME B. E. Prichard

TELEPHONE NO. (505) 374-3053

space for State Use)

ROVED BY [Signature] TITLE DISTRICT SUPERVISOR

DATE 2-5-98

DITIONS OF APPROVAL, IF ANY: