

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

NOTIFICATION OF FIRE, BREAKS, SPILLS, LEAKS, AND BLOWOUTS

NAME OF OPERATOR				Amoco Production Company				ADDRESS				P. O. Box 832, Brownfield, TX 79316																			
REPORT OF	FIRE	BREAK	SPILL	LEAK	BLOWOUT	OTHER*																									
				X																											
TYPE OF FACILITY	DRLG WELL	PROD WELL	TANK BTY	PIPE LINE	GASO PLNT	OIL RFY	OTHER*																								
				X																											
NAME OF FACILITY												Bravo Dome CO ₂ Gas Unit SE Collection System - Phase II																			
LOCATION OF FACILITY (QUARTER/QUARTER SECTION OR FOOTAGE DESCRIPTION)												SW/NE		SEC.	33	TWP.	21N	RGE.	33E	COUNTY	Harding										
DISTANCE AND DIRECTION FROM NEAREST TOWN OR PROMINENT LANDMARK												10 miles WNW of Hayden, NM																			
DATE AND HOUR OF OCCURRENCE												7:32 a.m.		3-12-88		DATE AND HOUR OF DISCOVERY				9:00		3-13-88									
WAS IMMEDIATE NOTICE GIVEN?		YES	X	NO	NOT REQUIRED		IF YES, TO WHOM		Roy Johnson																						
BY WHOM												D. J. Holcomb, Sr. Adm. Analyst								DATE AND HOUR				8:35 a.m.		3-14-88					
TYPE OF FLUID LOST												None - CO ₂ Gas Only								QUANTITY OF LOSS		N/A		BO		VOLUME RECOVERED		N/A		BO	
DID ANY FLUIDS REACH A WATERCOURSE?		YES		NO	X		QUANTITY																								
IF YES, DESCRIBE FULLY**																															
DESCRIBE CAUSE OF PROBLEM AND REMEDIAL ACTION TAKEN**																															
At 7:32 am on 3-12-88, a leak developed in the collection system at Well No. 2133-331G. The well has 4" fiberglass line pipe that connects to the 6" steel collection system. There is approx. 4' of steel 4" at the tie-in point. The 4" steel pup joint split and CO ₂ vented to atmosphere. The leak not detected until the next day (Sunday) 3-13-88 at 9:00 am.																															
DESCRIBE AREA AFFECTED AND CLEANUP ACTION TAKEN**																															
No fluid lost. Dirt blown away from line. Area will be repacked with top soil and reseeded if necessary to establish regrowth.																															
DESCRIPTION OF AREA		FARMING		GRAZING		X		URBAN		OTHER*																					
SURFACE CONDITIONS		SANDY		SANDY LOAM		X		CLAY		ROCKY		WET		X		DRY		SNOW		X											
DESCRIBE GENERAL CONDITIONS PREVAILING (TEMPERATURE, PRECIPITATION, ETC.)**																															
Approximately 25°F, winds N at 20 MPH, cloudy skies, occasional snow.																															
I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF																															
SIGNED		<i>DJ Holcomb</i>										TITLE				Sr. Admin. Analyst				DATE		3-14-88									
*SPECIFY		**ATTACH ADDITIONAL SHEETS IF NECESSARY																													

0+1 NMOCD

1-J. F. Trickett, Houston-Rm. 3.256

1-LF 1-DJH

At 11:00 am the collection system was isolated by a block valve and allowed to vent itself down. The leak was repaired 3-14-88 and returned to service.

Estimated Vent

Blowdown -	205 MCF
Leak -	<u>12,000 MCF</u>
TOTAL	12,205 MCF