

P-21-14N-33E: From above, attempted to reach well reportedly drilled by same operator (Underwood) as H-22-14N-33E and other wells in area. Landowner verified well as being in location described but believed drifting sand may have obscured casing and other signs of operation. Could not reach location due to vehicle's inability to cross deep sand drifts. 3/21/75 C.U. Land now owned by Bruhn.