

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☐ GAS ☐ OTHER- P&A

2. Name of Operator
Yates Petroleum Corporation

3. Address of Operator
207 South 4th St., Artesia, NM 88210

4. Location of Well
UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM
THE West LINE, SECTION 32 TOWNSHIP 11N RANGE 27E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
T-4 Cattle Co.

9. Well No.
2

10. Field and Pool, or Wildcat
Und. Penn

15. Elevation (Show whether DF, RT, GR, etc.)
4330.2' GR

12. County
Quay

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon well as follows:

- 1) Set CIBP @ 4860' and cap w/5 sx cement.
- 2) Cut and pull 5-1/2" casing from 2400'.
- 3) Spot plug through tubing from 2500' up to 2300' - 50 sx cement (Yeso top 2364').
This plug to be tagged with tubing after setting.
- 4) Spot plug from 2180' up to 2080' - 25 sx cement (Glorieta top 2133').
- 5) Spot plug from 1750 up to 1650' - 35 sx cement (San Andres top 1698').
- 6) Spot plug from 430' up to 320' - 50 sx cement (13-3/8" casing set @377').
This plug to be tagged with tubing after setting.
- 7) Set 15 sx cement plug and regulation abandonment marker at surface.

Note: One additional plug may be required between 1650' and 430' following NMOCD review of well logs.

Verbal approval to plug back to 1650' given by Mr. Roy Johnson, NMOCD, Santa Fe, on 5-17-84.

Note: Notify Mr. Roy Johnson, NMOCD, Santa Fe, 24 hours prior to commencing plugging operation. Phone No. 827-5800.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Quanta Goodlett

TITLE Production Supervisor

DATE 5-17-84

APPROVED BY Roy Johnson

TITLE Oil and Gas Supervisor

DATE 5-22-84

CONDITIONS OF APPROVAL, IF ANY:

25 sx cement plug @ 1060