

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals, and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-037-20037

5. Indicate Type of Lease

STATE ☐

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well

OIL
WELL ☐

GAS
WELL ☐

OTHER

CO2

2. Name of Operator

AMOCO PRODUCTION COMPANY

3. Address of Operator

P.O. Box 303, AMISTAD, NEW MEXICO 88410

8. Well No.

1736-281J

9. Pool name or Wildcat

BRAVO DOME CO2 GAS UNIT

4. Well Location

Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line
Section 28 Township 17N Range 36E NMPM Quay County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4325

CS

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations
SEE RULE 1103.

(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

11/16/99

MIRUSU

11/17/99

Kill well with fresh water, NUBOP, release packer, lay down production tubing and packer, run CIBP on wireline and set at 2126', run workstring and tag CIBP at 2126', displace casing with fresh water and corrosion inhibitor, pressure test casing to 500 psi, ok. Spot 10 sacks of class C cement from 2126' - 2068', pull workstring to 1457' and spot 25 sacks of cement from 1457' - 1312', pull workstring to 30', spot 5 sacks of cement from 30' - 3', NDBOP, RDMOSU, cut off wellhead, install PXA marker, cut off well anchors and clean location.

2/7/00
OK REF

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Danny J. Holcomb

TITLE Field Foreman

DATE 11-19-99

TYPE OR PRINT NAME Danny J. Holcomb

TELEPHONE NO. (505) 374-3010

(This space for State Use)

APPROVED BY Ry E Johnson

TITLE DISTRICT SUPERVISOR

DATE 2/10/00

CONDITIONS OF APPROVAL, IF ANY