

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

NOV 12 1980

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ CO₂ OTHER-

Name of Operator

Amoco Production Company

Address of Operator

P. O. Box 68 Hobbs, NM 88240

Location of Well

UNIT LETTER K 1980 FEET FROM THE South LINE AND 1980 FEET FROM
THE West LINE, SECTION 2 TOWNSHIP 19-N RANGE 34-E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

Hutcherson B

9. Well No.

5

10. Field and Pool, or Wildcat

Und. Tubb

15. Elevation (Show whether DF, RT, GR, etc.)

4786' GL

12. County

Union

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☒

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOBS ☒

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

On 10-5-80, CO₂ in Action (Rig #18) spudded a 12-1/4" hole at 3:30 p.m. Drilled to a TD of 700' and ran 8-5/8" casing set at 700'. Cemented with 400 SX Class C cement. Plugged down at 5:30 p.m. 10-6-80. Circulated 45 SX. WOC 20 hrs. Tested casing with 1000# for 30 min. Test OK. Reduced hole to 7-7/8" and resumed drilling. Drilled to a TD of 2614' and drill pipe stuck. Backed off at 2077'. Ran wash pipe to wash thru bridge at 1205'. Left Bit, 18 drill collars, and crossover sud and 97' of wash pipe and shoe..

Propose to P X A per the following procedure:

Spot a Class C cement plug 1100'-650'.
Spot a Class C surface plug.
Install P X A marker.

0+2-NMOCD, SF 1-Hou 1-Susp 1-LBG

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bob Davis TITLE Admin. Analyst

DATE 10-29-80

APPROVED BY Carl Deloag TITLE SENIOR PLANTATION GEOLOGIST

DATE 11/12/80

CONDITIONS OF APPROVAL, IF ANY: