

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 37501

Form C-103
Revised 10-1-

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☐ Fee ☐ 5. State Oil & Gas Lease No.
1. OIL WELL ☐ GAS WELL ☒ OTHER- <u>CO2</u>		7. Unit Name and Location <u>Bravo Dome Carbon Dioxide Gas Unit</u>
2. Name of Operator <u>AMOCO PRODUCTION COMPANY</u>		8. Field and Pool or Widespread <u>Bravo Dome Carbon Dioxide Gas Unit</u>
3. Address of Operator <u>P. O. Box 68, Hobbs, NM 88240</u>		9. Well No. <u>1935 031G</u>
4. Location of well UNIT LETTER <u>G</u>, <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>19-N</u> RANGE <u>35-E</u> N.M.P.M.		10. Field and Pool or Widespread <u>Bravo Dome Carbon Dioxide Gas Unit 240-Acre Area</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4585' GL</u>		12. County Union

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MI and RUSU 1-7-87. POH with production equipment. Frac down 2-7/8" worksheet, 230 bbls 40# HCL gelled 2% KCL FW and 70 tons CO2, 49414# 8/16 SN. Air 17 BPM and avg pressure 3300# ISIP 3000. Clean out sand to 2455 ft. Run 5 jts 2-7/8" tailpipe, packer and tubing. Packer set at 1951 ft. RD and MOSU 1-11-87. Flw test well. Return to production.

PPWO: 1057 MCFD 1 BWPD at 192# FTP.
PAWO: 1831 MCFD 30 BWPD at 183# FTP.

0+2-NMOCDF, SF 1-R.A. Sheppard HOU. Rm. 20.156 1-J.F. Nash HOU. Rm. 17.188 1-SBB
1-CMH 1-Amerada Hess 1-Amerigas 1-Cities Service 1-Conoco 1-CO2 in Action 1-Shell
1-Exxon 1-WF, Hobbs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Steve Brownlee

TITLE Admin. Analyst

DATE 2-24-87

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: