

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - C-1031 FOR SUCH PROPOSALS.

<p>1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> CO2 <input type="checkbox"/> OTHER</p> <p>2. Name of Operator Amoco Production Company</p> <p>3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240</p> <p>4. Location of Well UNIT LETTER <u>0</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>21</u> TOWNSHIP <u>23-N</u> RANGE <u>34-E</u> N.M.P.M.</p> <p>15. Elevation (Show whether DF, RT, CR, etc.) 4890' GL</p>	<p>7. Unit Agreement Name BDCDGU</p> <p>8. Farm or Lease Name BDCDGU 2334</p> <p>9. Unit No. 211</p> <p>10. Field and Pool, or Acreage Und. Tubb</p> <p>12. County Union</p>
--	---

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER _____ <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input checked="" type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER _____ <input type="checkbox"/></p> <p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOBS <input type="checkbox"/></p> <p>OTHER _____ <input type="checkbox"/></p> <p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input type="checkbox"/></p>
---	--

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon per the following method:

Run 2-3/8" tubing and circulate well with heavy mud. Spot 25 sacks class H cement on top of cast iron bridge plug set at 2697'. Spot 25 sacks class H cement across top of San Andres (approx. 1900' - 2090'.) Spot 25 sacks class H cement across 8-5/8" casing shoe. Spot 10 sacks class H cement plug at surface. Weld on cap. Erect abandonment marker. Fill pits, level location and clear area of junk.

0+2-NMOCD,SF 1-Hou 1- Susp 1-CLF 1-Amerada 1-UGI 1-Cities Serv.
1-Conoco 1-Co2 in Action 1-Excelsior 1-Sun Tex

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cathy L. Jorman TITLE Asst. Admin. Analyst DATE 10-26-82

APPROVED BY Carl Meyer TITLE DISTRICT MANAGER DATE 10/27/82

CONDITIONS OF APPROVAL, IF ANY: