

DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side)
GEOLOGICAL SURVEY

Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

MOO-C-1420-0982

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Isleta Pueblo

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Isleta Central

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

Cactus Area

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

NW/4 NW/4 Section 7-T7N-R2E

12. COUNTY OR PARISH

Valencia

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Drilling Well

2. NAME OF OPERATOR
Shell Oil Company

3. ADDRESS OF OPERATOR
1700 Broadway, Denver, Colorado 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

810' FNL & 640' FWL Section 7

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5066 KB, 5044 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) Set cmt plug ☒

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

(Other) ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Cut csg, perf & P&A ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(Other) ☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Verbal approval received from Mr. Jerry Long to cut csg, perf for water test, set plugs and abandon as follows:

Cmt across and 50' above Menefee perfs 12,209-12,345. Cut 7" csg. Place 100' plug across stub (50' inside and 50' outside). Place 150' plug across btm of 9-5/8" csg (75' inside and 75' outside). Perf 2600-2650 (USGS test). Place cmt across and 50' above 2600. Perf 1310-1390 (USGS test). Place cmt plug across and 50' above 1310. Place 20 sx @ surface. (Do not install abandonment marker unless requested by BIA) Perf'd and tested Menefee 12,209-12,345. Rec'd gas; too small to measure. Spt'd 100 sx cmt w/top @ 12,120.

18. I hereby certify that the foregoing is true and correct

SIGNED J. W. Linnell

TITLE Div. Oprs. Engr.

DATE 7/18/75

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

cc: Oil & Gas Conservation Commission - Santa Fe, N.M.

Southern Pueblo Agency

*See Instructions on Reverse Side