Good afternoon Gentlemen,

I was on site late yesterday afternoon and then again this morning. All the released fluid that was outside the secondary containment is overspray and all remained on location, nothing off the pad was impacted. My guys hand spotted a line today and did a little shovel work between the fence and the secondary containment. As soon as the one call clears, we will get to work excavating the impacted soil up and placing it on plastic for disposal. We'll excavate it down and conduct chloride field test as we go along. Upon getting favorable field test results, samples for lab analysis will be obtained and analyzed. I'll advise when we are about ready to sample.

Thanks, Vernon K. Black Hungry Horse, LLC PO Box 1058 Hobbs, NM 88241 575-393-3386 office 575-631-2253 cell

From: Zack Thomas [mailto:zthomas@mewbourne.com]
Sent: Thursday, July 24, 2014 1:32 PM
To: dwhitloc@blm.gov; Bratcher, Mike, EMNRD; Vernon Black
Subject: Maverick 13 DM Fed Com #1H C141 initial

homes

Zack Thomas Mewbourne Oil Company <u>PO Box 5270</u> Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252 (575) 602-2188 Email: <u>zthomas@Mewbourne.com</u>