

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Rec'd 10/30/14
NMOCD-Art

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Devon Energy Production	Contact	Tracy Kidd
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575.513.0628
Facility Name	Remuda Basin SWD 1	Facility Type	Salt Water Disposal Well
Surface Owner Federal	Mineral Owner Federal	API No. 30-015-29549, RPI 2350, NMNM-0543827	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	20	23S	30E	330	North	660	West	Eddy

Latitude: 32.2966716

Longitude: -103.90964

NATURE OF RELEASE

Type of Release Produced	Water Spill	Volume of Release	30BBLS	Volume Recovered	30BBLS
Source of Release	water tank	Date and Hour of Occurrence	6/10/2014 10:00 AM	Date and Hour of Discovery	6/10/2014 10:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos/BLM & Rich Inge/OCD		
By Whom?	Lynn Smith/ Asst Production Foreman	Date and Hour	6/10/2014 @ 1:30 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* Water tanks on location ran over and spilled into the lined containment surrounding the water tanks. The answering service never received an alarm, therefore the lease operator never received an alert about the overflow. It is suspected the issue was a result of bad weather as storms had passed through recently. Issues regarding the alarm system are being researched.					
Describe Area Affected and Cleanup Action Taken.* The 30BBLS of produced water that spilled from the water tank all spilled into lined containment. All 30BBLS were recovered. No further action is required.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sandra Farley</i>	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Sandra Farley			
Title: Field Admin Support	Approval Date: 11/18/14	Expiration Date: N/A	
E-mail Address: Sandy.Farley@dv.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>	
Date: June 13, 2014 Phone: 575.746.5587	Final		

* Attach Additional Sheets If Necessary