

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action****OPERATOR**☐ Initial Report ☒ Final Report


Name of Company: BOPCO, L.P.	Contact: Bradley Blevins	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: JRU #62 The flow line spill is 1,600 ft. north of the well pad; 2RP #2465	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-35340

**LOCATION OF RELEASE**

Unit Letter J	Section 1	Township 23S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude: N 32.334352° Longitude: W 103.832156°

**NATURE OF RELEASE**

Type of Release: crude oil and produced water	Volume of Release: 2 bbls crude oil and 8 bbls produced water	Volume Recovered: none
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence: 8/31/14 @ unknown	Date and Hour of Discovery: 8/31/14 @ approx. 11:44 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* The flow line leaked due to external corrosion. The well was shut in and a temporary repair clamp was installed on the affected pipe.		
Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 720 sq. ft. of caliche road. All of the fluid soaked into the roadway. The release area was excavated and contaminated soil hauled to a state approved disposal facility. Based on laboratory analytical data and NMOCD approval the excavation has been backfilled with clean soil. The area has been remediated in accordance to the NMOCD and BLM guidelines for spill remediation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 		<b>OIL CONSERVATION DIVISION</b>
Printed Name: Bradley Blevins		Approved by Environmental Specialist:
Title: Assistant Remediation Foreman	Approval Date: 3/5/2015	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2-18-15	Phone: 432-214-3704	FINAL

\* Attach Additional Sheets If Necessary

2RP-2465