

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1611835288

OPERATOR☐ Initial Report ☒ Final Report

Name of Company Matador Resources	Contact Catherine Green
Address 500 N Main St Suite 1 Roswell NM 88201	Telephone No. 575-623-6601
Facility Name Parker Deep 5 Fed 3	Facility Type Oil Well

Surface Owner	Mineral Owner Federal	API No. 30-015-32555
---------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter N	Section 05	Township 18S	Range 31E	Feet from the 990	North/South Line FSL	Feet from the 1980	East/West Line FWL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude_32.7720222_ Longitude_ -103.8939056 _

NATURE OF RELEASE

Type of Release fluid from heater treater	Volume of Release ~10 barrels	Volume Recovered
Source of Release heater treater	Date and Hour of Occurrence April 24, 2016	Date and Hour of Discovery April 24, 2016 12:30pm
Was Immediate Notice Given? Required <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Catherine Green	
By Whom? Anthony Sanchez	Date and Hour April 24, 2016 12:45pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Hole in fire tube in heater treater caused leak into secondary containment. Excess fluid was vacuumed up. Soil samples will be collected at various depths and remediation will be performed.

Describe Area Affected and Cleanup Action Taken.*

Leak was contained in containment area. Excess fluid was vacuumed up and removed. Soil containing unsatisfactory levels of BTEX, DROs, and chlorides was removed and replaced. See attached.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISIONSignature: *Catherine S Green*

Printed Name: Catherine Green

Approved by Environmental Specialist: *M Bratcher*

Title: Regulatory Analyst	Approval Date: 8/22/2016	Expiration Date: N/A
E-mail Address: cgreen@matadorresources.com	Conditions of Approval: N/A Final Report	Attached
Date: August 19, 2016, 2016 Phone: 575-623-6601		

2RP-3660

