

Received 9/7/2016

NMOCD Dist 2

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

unk **Release Notification and Corrective Action**

unk **OPERATOR** ☐ Initial Report ☒ Final Report

Name of Company Enterprise Field Services LLC	Contact Alena Miro
PO Box 4324, Houston, TX 77210	Telephone No. 575-706-4926
Facility Name Pipeline ROW, Eddy County Trunk A	Facility Type: Gas Gathering Pipeline
Gathering Lateral *2RP-3187*	

Surface Owner Bureau of Land Management	Mineral Owner NA - Pipeline	Lease No. NA
--	------------------------------------	---------------------

LOCATION OF RELEASE

Unit Letter N	Section 8	Township 23S	Range 31E	Feet from the 145	North/South Line North	Feet from the 474	East/West Line West	County Eddy
-------------------------	---------------------	------------------------	---------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------

Latitude: **N 32.314966** Longitude: **W -103.802581**

NATURE OF RELEASE

Type of Release Natural Gas, Pipeline Liquids	Volume of Release: 380 MCF, 5 BBL Liquids	Volume Recovered: N/A
Source of Release Pipeline Leak.	Date and Hour of Occurrence 04/29/2015 @ 13:00 MDT	Date and Hour of Discovery 04/29/2015 @ 13:00 MDT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD District 2	
By Whom? Osman De Leon	Date and Hour 04/29/2015 @ 15:56 MDT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Pipeline leak was detected by pumper passing by. Pipeline segment was isolated, blown down and clamped, and the leaking portion was repaired following standard One-Call.

Describe Area Affected and Cleanup Action Taken.*

Liquid spill occurred within pipeline ROW with liquid overspray outside of ROW. Cleanup activities were completed in accordance with Enterprise's General Release Notification, Response and Remediation Plan (dated March 9, 2015) and the attached closure plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jon E. Fields	Approved by District Supervisor: Accepted for Record	
Title: Director, Field Environmental	Approval Date: 9/8/16	Expiration Date: 9/8/16
E-mail Address: jefields@eprod.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 9/7/2016 Phone: 713-381-6684	FINAL	

* Attach Additional Sheets If Necessary

NOTE: Initial report for this release is not located in data base. Remediation was performed under 2RP-3187 per closure report.