

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico NMOCD Dist 2
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

fAB15126726679

Release Notification and Corrective Action

nAB1526726825

OPERATOR

Initial Report Final Report

Name of Company <i>Enterprise Field Services LLC</i>		Contact <i>Alena Miro</i>
<i>PO Box 4324, Houston, TX 77210</i>		Telephone No. <i>575-706-4926</i>
Facility Name <i>Lateral</i>	<i>Pipeline ROW, 58475OPV Gathering</i>	Facility Type: <i>Gas Gathering Pipeline</i>
Surface Owner <i>Bureau of Land Management</i>	Mineral Owner <i>NA - Pipeline</i>	Lease No. <i>NA</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>I</i>	<i>5</i>	<i>23S</i>	<i>26E</i>	<i>266</i>	<i>South</i>	<i>260</i>	<i>West</i>	<i>Eddy</i>

Latitude: *N 32.330724* Longitude: *W -104.310416*

NATURE OF RELEASE

Type of Release <i>Natural Gas, Pipeline Liquids</i>	Volume of Release: <i>570 MCF, 5 BBL Liquids</i>	Volume Recovered: <i>N/A</i>
Source of Release <i>Pipeline Leak.</i>	Date and Hour of Occurrence <i>09/04/2015 @ 15:30 MDT</i>	Date and Hour of Discovery <i>09/04/2015 @ 15:30 MDT</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? <i>Osman De Leon</i>	Date and Hour <i>9/4/2015 @ 19:30 MDT</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Pipeline leak was discovered by Enterprise operations. Pipeline segment was isolated, blown down and clamped; leaking portion was repaired following standard One-Call.

Describe Area Affected and Cleanup Action Taken.*

Liquid spill occurred within pipeline ROW. Cleanup activities were carried out in accordance with Enterprise's General Release Notification, Response and Remediation Plan (dated March 9, 2015).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: <i>Jon E. Fields</i>	Approved by District Supervisor: <i>MBratcher</i>	
Title: <i>Director, Field Environmental</i>	Approval Date: <i>10/13/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>jefields@eprod.com</i>	Conditions of Approval: <i>N/A</i>	Attached <input type="checkbox"/>
Date: <i>10/11/2016</i> Phone: <i>713-381-6684</i>	FINAL	

* Attach Additional Sheets If Necessary

2RP-3295