

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 10/17/2016
NMOCD Dist 2

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1613742363

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	PO Box 4294, Houston, TX 77210	Telephone No.	(575) 513-8289
Facility Name	Lost Tank 3 Federal #21	Facility Type	Well

Surface Owner	State	Mineral Owner	API No.	30-015-37920
---------------	-------	---------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	3	22S	31E					Eddy County, NM

Latitude N 32.42074° Longitude W 103.77336°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	15 bbls oil, 5 bbls produced water	Volume Recovered	14 bbls
Source of Release	Excess pressure caused the stuffing box packing on the wellhead to blow out	Date and Hour of Occurrence	05/03/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD, Shelly Tucker- BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	05/03/2016 @ 4:01 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Excess pressure caused the stuffing box packing on the wellhead to blow out 15 bbls of oil and 5 bbls of produced water onto location. A vacuum truck recovered 14 bbls of fluids and the stuffing box packing was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 175' x 150' with most of the leak staying on location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 09/02/2016 and approved by Shelly Tucker of the BLM via email on 08/29/2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Casey Summers	Approved by Environmental Specialist: <i>MBratcher</i>		
Title: NM Environmental Advisor	Approval Date: 10/17/16	Expiration Date: N/A	
E-mail Address: Casey.Summers@oxy.com	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: 10-12-16 Phone: (575) 513-8289	FINAL		

* Attach Additional Sheets If Necessary

2RP-3693