

**From:** [Groves, Amber](#)  
**To:** [Robert McNeill](#); [Bratcher, Mike, EMNRD](#); [Patterson, Heather, EMNRD](#); [Strang, Dana V.](#); [Martin, Ed](#); [Naranjo, Mark M.](#)  
**Subject:** RE: Willow 17 State SWD #1 - C141  
**Date:** Tuesday, June 07, 2016 3:15:19 PM  
**Attachments:** image001.png  
image003.png

---

Good Afternoon, Mr. McNeill,

Do you have any photos and/or the dimensions of this release?

Thank you,

**Amber Groves**

*Remediation Specialist*

*Field Operations Division*

(575)392-3697

(575)263-3209 cell

New Mexico State Land Office

2827 N. Dal Paso Suite 117

Hobbs, NM 88260

.....  
**CONFIDENTIALITY NOTICE** - This e-mail transmission, including all documents, files, or previous e-mail messages attached hereto, may contain confidential and/or legally privileged information. If you are not the intended recipient, or a person responsible for delivering it to the intended recipient, you are hereby notified that you must not read this transmission and that any disclosure, copying, printing, distribution, or use of any of the information contained in and/or attached to this transmission is STRICTLY PROHIBITED. If you have received this transmission in error, please immediately notify the sender and delete the original transmission and its attachments without reading or saving in any manner. Thank you.

---

**From:** Robert McNeill [mailto:RMcNeill@concho.com]  
**Sent:** Tuesday, June 07, 2016 2:29 PM  
**To:** Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Patterson, Heather, EMNRD (Heather.Patterson@state.nm.us) <Heather.Patterson@state.nm.us>; Groves, Amber <agroves@slo.state.nm.us>; Strang, Dana V. <dvstrang@slo.state.nm.us>; Martin, Ed <emartin@slo.state.nm.us>; Naranjo, Mark <MNaranjo@slo.state.nm.us>  
**Subject:** Willow 17 State SWD #1 - C141

Mr. Bratcher/Ms. Groves,

COG Operating LLC is reporting a release on the Willow 17 State SWD #1 (30-015-41806)  
Unit P Section 17 Township 25S Range 28E

The release occurred at 2:00 pm on 5/27/2016

Released: 15 bbls PW

Recovered: 0 bbls PW

This release was caused by a check valve on a poly flowline. The broken check valve was replaced. Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Robert McNeill, P. E.  
Environmental Manager  
COG Operating LLC

One Concho Center  
600 West Illinois Avenue  
Midland, TX 79701  
Office 432.221.0388  
Cell 432.638.6470

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---