From: <u>Weaver, Crystal, EMNRD</u>

To: "Blaney, Karolina"; Groves, Amber

Cc: Bratcher, Mike, EMNRD

Subject:RE: WPX Pinnacle 32-36 - initial C-141Date:Friday, January 6, 2017 1:23:00 PMAttachments:1. 4058 - COAs & signed C-141 initial.pdf

RE: WPX Energy Inc. \* Pinnacle 36-32H \*30-015-41587 \* 2RP-4058

Karolina,

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4058.

Thank you,

# **Crystal Weaver**

Environmental Specialist OCD – Artesia District II

811 S. 1<sup>st</sup> Street

Artesia, NM 88210

Office: 575-748-1283 ext. 101

Cell: 575-840-5963 Fax: 575-748-9720

**From:** Blaney, Karolina [mailto:Karolina.Blaney@wpxenergy.com]

Sent: Monday, January 2, 2017 4:58 AM

To: Groves, Amber <agroves@slo.state.nm.us>

Cc: Weaver, Crystal, EMNRD < Crystal. Weaver@state.nm.us>; Bratcher, Mike, EMNRD

<mike.bratcher@state.nm.us>

Subject: RE: WPX Pinnacle 32-36 - initial C-141

#### Good morning,

Attached is the initial C-141 for the Pinnacle 36-32 oil spill which occurred on 12/21/16.

Please let me know if you have any questions or suggestions.

Thank you and have a great day,

## Karolina Blaney

Environmental Specialist

WPX Energy

Office: (575) 885-7514 Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Blaney, Karolina

**Sent:** Wednesday, December 21, 2016 10:53 AM **To:** Groves, Amber <a href="mailto:agroves@slo.state.nm.us">agroves@slo.state.nm.us</a>>

**Cc:** 'Weaver, Crystal, EMNRD' < <a href="mailto:Crystal.Weaver@state.nm.us">Crystal.Weaver@state.nm.us</a>; 'Patterson, Heather, EMNRD' < <a href="mailto:Heather.Patterson@state.nm.us">Heather.Patterson@state.nm.us</a>; 'Bratcher, Mike, EMNRD' < <a href="mailto:mike.bratcher@state.nm.us">mike.bratcher@state.nm.us</a>; 'Bratcher, Mike, EMNRD' < <a href="mailto:mike.bratcher.m

**Subject:** WPX Pinnacle 32-36 oil spill notification

#### Good morning,

This morning WPX discovered a small spill at the Pinnacle 32-36 well pad; API # 30-015-41587. The spill was caused by equipment failure; dumps on the heater treater were not working properly which resulted in oil spraying out of the flare. The spill migrated off location for approximately 40-50 yards southwest of the well pad. WPX would like to ask for permission to scrape off the impacted soil and sample the impacted area for further remediation.

The C-141 report will be submitted in the next 15 days.

Please let me know if you have any questions or suggestions.

Thank you,

### Karolina Blaney

Environmental Specialist WPX Energy

Office: (575) 885-7514 Cell: (970) 589-0743

karolina.blaney@wpxenergy.com