

From: [Weaver, Crystal, EMNRD](#)
To: "Rebecca Haskell"; [Bratcher, Mike, EMNRD](#); stucker@blm.gov
Cc: [Jim Amos \(jamos@blm.gov\)](mailto:jamos@blm.gov)
Subject: RE: (C-141 Initial) Burch Keely Water Flood Satellite C Flowline 12/22/16 (30-015-02971)
Date: Friday, January 6, 2017 1:55:00 PM
Attachments: [image002.png](#)
[1. 4052 - COAs & signed C-141 intial.pdf](#)

RE: COG Operating LLC. * Burch Keely Water Flood Satellite C * 30-015-02971 * 2RP-4052

Rebecca,

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4052.

Thank you,

Crystal Weaver

Environmental Specialist
OCD – Artesia District II
811 S. 1st Street
Artesia, NM 88210
Office: 575-748-1283 ext. 101
Cell: 575-840-5963
Fax: 575-748-9720

From: Rebecca Haskell [<mailto:RHaskell@concho.com>]
Sent: Wednesday, December 28, 2016 4:06 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; stucker@blm.gov
Cc: Jim Amos (jamos@blm.gov) <jamos@blm.gov>
Subject: (C-141 Initial) Burch Keely Water Flood Satellite C Flowline 12/22/16 (30-015-02971)

Mr. Bratcher / Ms. Tucker,

Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank You,

Becky Haskell

Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



From: Dakota Neel
Sent: Thursday, December 22, 2016 3:08 PM
To: Heather Patterson; Mike.Bratcher@state.nm.us; Weaver, Crystal, EMNRD; stucker@blm.gov; James_Amos@blm.gov
Cc: Robert McNeill; Rebecca Haskell
Subject: (Notification) Burch-Keely Water Flood Satellite "C" Flowline Leak

Mr. Bratcher/Ms. Tucker,

COG Operating LLC is reporting a release on the Burch-Keely Water Flood Satellite "C" Flowline.

Section 13 Township 17S Range 29E

The release occurred on 12-22-2016 at approximately 7:00 AM.

Estimated Released: Approx. 15 bbls of Oil & 25 bbls of Produced Water

Estimated Recovered: Approx. 10 bbls of Oil & 20 bbls of Produced Water.

This release was caused by a flowline leak on a buried fiberglass flowline. This release occurred on the lease road and in the pasture. A vacuum truck was dispatched to recover the standing fluid. This area is being evaluated and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Thank You,

Dakota Neel
HSE Coordinator
COG Operating LLC
Cell: 432-215-2783
dneel2@concho.com

2407 Pecos Ave.
Artesia, NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or

privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.