

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nKMW1104139783

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Chesapeake Operating, Inc. Chevron USA Inc.	Contact: Josepha DeLeon
Address: 5014 Carlsbad Highway, Hobbs, NM 88240 Chevron - 6301 Deauville Blvd., Midland, TX 79706	Telephone No.: 575-263-0424
Facility Name: Henshaw Deep #5	Facility Type: Production Well

Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-03913 <b>2RP-602</b>
--------------------	--------------------	--

#### LOCATION OF RELEASE

Unit Letter F	Section 23	Township 16S	Range 30E	Feet from the 660	North/South line South	Feet from the 660	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

#### NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 35 barrels	Volume Recovered: 25 barrels
Source of Release: Stuffing Box	Date and Hour of Occurrence: January 29, 2011 @ 11:00 am	Date and Hour of Discovery: January 29, 2011 @ 1:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, NMOCD – Artesia; Jim Amos, BLM	
By Whom? Bradley Blevins, Chesapeake Operating, Inc.	Date and Hour: January 29, 2011, 1:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A



Describe Cause of Problem and Remedial Action Taken.\*

Stuffing Box on well malfunctioned causing release of production fluids onto location.

Describe Area Affected and Cleanup Action Taken.\*

25 of 35 barrels were recovered and contaminated soil was excavated and hauled to state approved land farm. Soil samples were taken and submitted to Cardinal Laboratories. Area was backfilled and returned to proper conditions.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		<b>OIL CONSERVATION DIVISION</b>	
Signature:		Approved by Environmental Specialist: 	
Printed Name: Josepha DeLeon			
Title: Environmental Compliance Specialist		Approval Date: 8/22/17	Expiration Date: N/A
E-mail Address: jdx@chevron.com		Conditions of Approval:	
Date: August 21, 2017 Phone: 432-425-1528		Like approval by BLM	
		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-602