## **Bratcher, Mike, EMNRD**

**From:** Sheldon Hitchcock <slhitchcock@talonlpe.com>

**Sent:** Friday, September 1, 2017 1:23 PM

To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD
Cc: Clayton\_McDonald@oxy.com; David Adkins

**Subject:** UPDATE: Pecos River Station Oxy Unload Updated Initial/Final C-141

**Attachments:** 20170901130915283-signed.pdf

**Importance:** High

Mike,

As we discussed on the phone this is an update to the C-141 submitted on 8/24/2017. Our volumes were wrong on the first attachment. We believe the volume lost to be approximately 50bbls. All of the fluid was contained within the lined tank battery. We recovered approximately 50bbls of fluid, removed the stained gravel. We inspected the liner and determined it to be intact and in good condition. After the liner was inspected we installed clean gravel ballast. Please let me know if you have any questions or concerns.

Respectfully,

## **Sheldon Hitchcock**

Project Manager
Office: 575.746.8768
Direct: 575.616.4021
Cell: 575.689.5198
Fax: 575.746.8905

Emergency: 866.742.0742 Web: <u>www.talonlpe.com</u>

