From: Tucker, Shelly
To: Frank Barnett

Cc: Katherine Purvis; Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Casey Summers; Cliff Brunson; Ken

Swinney; Jennifer Gilkey

Subject: Re: Government T Com #001 South Oil Tank

Date: Tuesday, January 10, 2017 9:39:42 AM

Thank you for the corrected information.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist O&G Spill/Release Coordinator

Bureau of Land Management 620 E. Greene St Carlsbad, NM 88220

575.234.5905 - Direct 575.361.0084 - Cellular 575.234.6235 - Emergency Spill Number

stucker@blm.gov

The **BLM** acceptance/approval does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Tue, Dec 20, 2016 at 10:47 AM, <Frank Barnett@oxy.com> wrote:

The dimensions for the impacted area are incorrect. The actual size of the spill impact is 25' x 85'.

Thanks,

FRANK BARNETT

Oxy Permian Resources | HES Operations Coordinator | New Mexico Remediation | O: (575) 628-4004 | C: (575) 921-6352 | Frank_Barnett@Oxy.com

From: Kathy Purvis [mailto:kathy@bbcinternational.com]

Sent: Tuesday, December 20, 2016 8:55 AM

To: 'Bratcher, Mike, EMNRD' < <u>mike.bratcher@state.nm.us</u>>; <u>crystal.weaver@state.nm.us</u>;

stucker@blm.gov

Cc: Summers, Casey L < <u>Casey Summers@oxy.com</u>>; Barnett, Frank

< Frank Barnett@oxy.com >; Hudgens, Jennifer A < Jennifer Hudgens@oxy.com >; 'Cliff

Brunson' < cbrunson@bbcinternational.com; 'Ken Swinney'

< kswinney@bbcinternational.com>; 'Jennifer Gilkey' < jgilkey@bbcinternational.com>;

kathy@bbcinternational.com

Subject: Government T Com #001 South Oil Tank

This is to inform you that Oxy Permian had a release at the Government T Com #001 South Oil Tank on December 18, 2016. Oxy released 100 bbls of produced water due to failure of a gasket on the manway cover. The preliminary report indicates that the leak measures 6' X 600' inside the containment on location. A vacuum truck recovered 60 bbls of produced water. The release is located in U/L C, Section 14, T20S, R28E in Eddy County, NM. Driving directions are not available at this time. GPS coordinates: N 32.57850 W 104.15020 API# 30-015-20958

Kathy Purvis

BBC International, Inc.

1324 W. Marland Blvd.

Hobbs, NM 88240

Business: (575) 397-6388

Cell: (575) 441-8619

kathy@bbcinternational.com