

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 6/2/2017
NMOCD Dist 2

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1625342050

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	OXY USA INC	Contact	CASEY L SUMMERS
Address	PO BOX 4294; HOUSTON, TX 77210	Telephone No.	575-513-8289
Facility Name	Harroun 15 #3 & #5 CTB	Facility Type	SWD

Surface Owner	STATE	Mineral Owner	STATE	API No.	30-015-29233
---------------	-------	---------------	-------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	15	24S	29E	1657	NORTH	330	EAST	EDDY

Latitude N 32.22011 Longitude W 103.96463 NAD83

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	3 bbls oil, 7 bbls produced water	Volume Recovered	9 bbls
Source of Release	Compromised 2" steel line from the separator	Date and Hour of Occurrence	08/22/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	08/23/2016 @ 4:54 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A compromised 2" steel line from the separator leaked 3 bbls of oil and 7 bbls of produced water. A vacuum truck recovered 9 bbls of fluids and the line was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 10' x 20' both on and off location. Remediation was completed in accordance with the remediation plan approved for the release (2RP-3878) by Shelly Tucker of the BLM on 11/21/2016 and Mike Bratcher of the NMOCD on 11/29/2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: CASEY L SUMMERS		Approved by Environmental Specialist: 	
Title: ENVIRONMENTAL ADVISOR		Approval Date: 9/28/17	Expiration Date: N/A
E-mail Address: casey_summers@oxy.com		Conditions of Approval: Like Approval BLM	
Date: 6-2-17 Phone: 575-513-8289		FINAL Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-3878