

## Bratcher, Mike, EMNRD

---

**From:** Weaver, Crystal, EMNRD  
**Sent:** Friday, January 26, 2018 4:24 PM  
**To:** Raley, Jim; Blaney, Karolina; 'Tucker, Shelly'  
**Cc:** Bratcher, Mike, EMNRD  
**Subject:** RE: [EXTERNAL] RE: WPX/RKI RDU 45 - C-141

RE: WPX \* RDU 45 Well Pad \* 30-015-42018 \* 2RP-4519

Jim,

Thank you for the submission of the site characterization. However, the site map is lacking sampling points S2 and S3 being marked anywhere on the map. Since I am unaware of where the sample points I just mentioned are located in accordance with the spill plume I will say this, we definitely need to see lab data from a sample point as close to the point of release as possible which I see in your write up you say WPX is working on getting results for samples close to the point of release. Good. Also for the amount of area that this spill has traveled more delineation sample points than 3 will be required in order to properly define this spill plume. Please make sure to refer to the directions of the COA when conducting the delineation. No approval of a site characterization plan can be provided until the full delineation is achieved and all the lab data is presented.

Thank you,

### Crystal Weaver

Environmental Specialist  
OCD – Artesia District II  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210  
Office: 575-748-1283 ext. 101  
Cell: 575-840-5963  
Fax: 575-748-9720

---

**From:** Raley, Jim [mailto:James.Raley@wpxenergy.com]  
**Sent:** Wednesday, January 24, 2018 12:49 PM  
**To:** Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Blaney, Karolina <Karolina.Blaney@wpxenergy.com>; 'Tucker, Shelly' <stucker@blm.gov>  
**Cc:** Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>  
**Subject:** RE: [EXTERNAL] RE: WPX/RKI RDU 45 - C-141

RE: WPX \* RDU 45 Well Pad \* 30-015-42018 \* 2RP-4519

Please find attached site characterization and work plan proposal.  
Please contact me if you have any questions.

Jim Raley | Environmental Specialist - Permian Basin

5315 Buena Vista Dr., Carlsbad, NM 88220

C: (575)689-7597 | [james.raley@wpxenergy.com](mailto:james.raley@wpxenergy.com)



---

**From:** Weaver, Crystal, EMNRD [<mailto:Crystal.Weaver@state.nm.us>]

**Sent:** Wednesday, January 17, 2018 12:57 PM

**To:** Blaney, Karolina <[Karolina.Blaney@wpxenergy.com](mailto:Karolina.Blaney@wpxenergy.com)>; 'Tucker, Shelly' <[stucker@blm.gov](mailto:stucker@blm.gov)>

**Cc:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Raley, Jim <[James.Raley@wpxenergy.com](mailto:James.Raley@wpxenergy.com)>

**Subject:** [EXTERNAL] RE: WPX/RKI RDU 45 - C-141

---

CAUTION: This email was sent from an EXTERNAL source. Use caution when clicking links or opening attachments.

---

RE: WPX \* RDU 45 Well Pad \* 30-015-42018 \* 2RP-4519

Karolina,

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval (COA). The OCD tracking number for this event is 2RP-4519, please refer to this tracking number on any and all submissions sent in to the OCD. Please remit a site characterization plan (see COA document included in attachment) or advise OCD of plan of action by no later than 1/24/18.

Thank you,

## Crystal Weaver

Environmental Specialist

OCD – Artesia District II

811 S. 1<sup>st</sup> Street

Artesia, NM 88210

Office: 575-748-1283 ext. 101

Cell: 575-840-5963

Fax: 575-748-9720

---

**From:** Blaney, Karolina [<mailto:Karolina.Blaney@wpxenergy.com>]

**Sent:** Thursday, December 14, 2017 1:47 PM

**To:** Weaver, Crystal, EMNRD <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>; 'Tucker, Shelly' <[stucker@blm.gov](mailto:stucker@blm.gov)>

**Cc:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Raley, Jim <[James.Raley@wpxenergy.com](mailto:James.Raley@wpxenergy.com)>

**Subject:** RE: WPX/RKI RDU 45 - C-141

Good afternoon,

Attached is the C-141 report for the RDU 45 spill that occurred on 12/2/17.

Please let me know if you have any further questions or comments.

Thank you,

*Karolina Blaney*

Environmental Specialist

WPX Energy  
Office: (575) 885-7514  
Cell: (970) 589-0743  
[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)

---

**From:** Blaney, Karolina  
**Sent:** Sunday, December 03, 2017 10:37 AM  
**To:** Weaver, Crystal, EMNRD <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>; 'Tucker, Shelly' <[stucker@blm.gov](mailto:stucker@blm.gov)>  
**Cc:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Raley, Jim <[james.raleigh@wpxenergy.com](mailto:james.raleigh@wpxenergy.com)>  
**Subject:** WPX/RKI RDU 45 - initial spill notification

Good morning,

WPX had a small spill yesterday, 12/2/17, at 9:30 am at the RDU 45 well pad. API # 30-015-42018, M-22-26S-30E. The spill was caused by a failure of a buried flowline. Approximately 5 bbls of produced fluids were spilled on location with 2 bbls recovered. None of the spilled fluids has left the pad. I will submit the C-141 report in the next 14 days but please do not hesitate to contact me if you have any questions.

Thank you and have a great rest of the weekend.

*Karolina Blaney*  
Environmental Specialist  
WPX Energy  
Office: (575) 885-7514  
Cell: (970) 589-0743  
[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)