

## Bratcher, Mike, EMNRD

---

**From:** Mann, Ryan <rmann@slo.state.nm.us>  
**Sent:** Wednesday, June 6, 2018 2:08 PM  
**To:** 'larry.baker@apachecorp.com'  
**Cc:** Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD  
**Subject:** RE: 2RP-4506 Oxy Malt-O-Meal Battery CAP  
**Attachments:** LOAMY.docx

NMSLO has reviewed the corrective action plan. The plan is approved with the following comments:

- As stated in your report, SP-5 is not delineated and will be hand excavated with bottom and sidewalls samples submitted for lab analysis for chloride, extended TPH, and BTEX. Once the area around SP-5 is delineated a remediation plan can developed with consultation from NMOCD/NMSLO. Because the area is not delineated any remedial action will require agency approval.
- The report states the site will be reseeded with BLM #2, no seed mix information was attached. There are several seed mixes floating around, I want to ensure that you're using an appropriate mix. I have attached a mix that will work in the area, (BLM #2 may as well, I just don't know the contents)

NMOCD may have additional concerns. Please contact me if you have any questions.

Ryan Mann  
Remediation Specialist  
Field Operation Division  
(575) 392-3697  
(505) 699-1989  
New Mexico State Land Office  
2827 N. Dal Paso Suite 117  
Hobbs, NM 88240

---

**From:** Naranjo, Mark  
**Sent:** Monday, June 4, 2018 2:21 PM  
**To:** Mann, Ryan <rmann@slo.state.nm.us>  
**Subject:** FW: 2RP-4506 Oxy Malt-O-Meal Battery CAP

Mark Naranjo  
Assistant Division Director  
Field Operations Division  
575.623.4979 Office  
575.626.2678 Cell  
575.623.9200 Fax  
New Mexico State Land Office  
1001 S. Atkinson  
Roswell, NM 88203  
[MNaranjo@slo.state.nm.us](mailto:MNaranjo@slo.state.nm.us)  
[NMStatelands.org](http://NMStatelands.org)

CONFIDENTIALITY NOTICE: This e-mail, including all attachments is for the sole use of the intended recipient[s] and may contain confidential and/or privileged information. Any unauthorized review, use, copying, disclosure or distribution is prohibited, unless specifically provided under the New Mexico Inspection of Public Records Act. If you are not the intended recipient, please contact the sender at once and destroy all copies of this message

---

**From:** Baker, Larry [<mailto:Larry.Baker@apachecorp.com>]

**Sent:** Monday, June 4, 2018 1:25 PM

**To:** Bratcher, Mike, EMNRD ([mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)) <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Weaver, Crystal, EMNRD <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>; Naranjo, Mark <[MNaranjo@slo.state.nm.us](mailto:MNaranjo@slo.state.nm.us)>

**Subject:** 2RP-4506 Oxy Malt-O-Meal Battery CAP

All,

Attached is the corrective action plan proposal for your review. Please let me know if you have any questions or wish to discuss. Thanks and have a good day.

## BRUCE BAKER

ENVIRONMENTAL TECHNICIAN SR

*direct* 575-393-7106 ext 1523 | *Cell* 432-631-6982

APACHE CORPORATION

2350 W. MARLAND BLVD

HOBBS, NM 88240

[ApacheCorp.com](http://ApacheCorp.com) | [LinkedIn](#) | [Facebook](#) | [Twitter](#) | [StockTwits](#) | [YouTube](#)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---