

From: [Pruett, Maria, EMNRD](#)
To: ["larrym_gdc@hotmail.com"](mailto:larrym_gdc@hotmail.com)
Cc: [Bratcher, Mike, EMNRD](#); [Mann, Ryan](#)
Subject: FW: Notification of Spill API: 30-005-60949 Tamarack
Date: Friday, July 20, 2018 9:12:00 AM
Attachments: [Tamarack001a7-11-18.jpg](#)
[Tamarack0017-11-18.jpg](#)

Good Morning Mr. Marks,

I'd like to introduce myself, I am the new ES here in District 2 and I look forward to working with you all in the future.

One of our inspectors observed a possible tank leak at the Tamarack site API:30-005-60949. Please see attached photos.

Let me know if you have any questions or need any further information.

Best Regards,

Maria Pruett

Environmental Specialist
N.M. Oil Conservation Division
District 2
811 S. 1st Street
Artesia, NM 88210
Desk: 575 748-1283 X 101
Cell: 575 840-5963
Fax: 575748-9720

From: Cordero, Gilbert, EMNRD
Sent: Wednesday, July 11, 2018 3:15 PM
To: Pruett, Maria, EMNRD <Maria.Pruett@state.nm.us>
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Subject: Tamarack

Maria,

Attached are pictures of the Tamarack QF State Battery that is on the same location as the Tamarack QF State 001, 30-005-60949. It appears that the overflow tank is leaking and also maybe the plumbing. The last time I talked to Mr. Marker he told me that he would remove the overflow tank because it was leaking.

Thank you,

Gilbert Cordero

Staff Manager

NMOCD District II

Office 575.748.1283 ext.114

Cell 575.626.0830