District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural **Resources Department** 

**Oil Conservation Division** 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

)

Page 1 of 2

Incident ID	NVV2003433576
District RP	
Facility ID	
Application ID	

# **Release Notification**

## **Responsible Party**

Responsible Party: WPX Energy Permian, LLC.	OGRID: 246289
Contact Name: Lynda Laumbach	Contact Telephone: (575) 725-1647
Contact email: Lynda.Laumbach@wpxenergy.com Incident # (assigned by OCD)   NVV2003433576	
Contact mailing address: 5315 Buena Vista Drive, Carlsbad, NM 88220	

#### **Location of Release Source**

32.020878 Latitude

-103.974639 Longitude (NAD 83 in decimal degrees to 5 decimal places)

Site Name: East Pecos Federal 22 #009H	Site Type: Production Facility
Date Release Discovered: 01/21/2020	API# (if applicable): 30-015-43349

Unit Letter	Section	Township	Range	County
М	22	26S	29E	Eddy

Surface Owner: State Federal Tribal X Private (Name: \_

# **Nature and Volume of Release**

	Material(s) Released (Select all that apply and attach calc	ulations or specific justification for the volumes provided below)
ude Oil	Volume Released (bbls)	Volume Recovered (bbls)

Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
X Produced Water	Volume Released (bbls): 140	Volume Recovered (bbls): 115
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	X Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release:

A swedge connection on the transfer pump failed, causing 140bbls to be released onto the pad and inside the tank battery lined secondary containment. A vacuum truck was immediately called and recovered 115bbl of fluids. A third-party contractor has been obtained to complete remediation activities. Soil estimates on the pad surface were saturated soil volume  $(ft^3)$ 

$$bbl estimate = \frac{suturated soil volume (ft)}{4.21(\frac{ft^3}{bbl equivalent})} * estimated soil porosity(\%)$$

Oil Conservation Division ES, for what reason(s) does the responsible parase was greater than 25bbls	Incident ID District RP Facility ID Application ID	NVV2003433576
	Application ID	?
		?
	ty consider this a major release	?
5	iven to the OCD? By whom? To whom? Wh	iven to the OCD? By whom? To whom? When and by what means (phone,

## **Initial Response**

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 $\overline{\mathbf{X}}$  The source of the release has been stopped.

 $\overline{\mathbf{X}}$  The impacted area has been secured to protect human health and the environment.

X Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

 $\overline{\mathbf{X}}$  All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Lynda Laumbach	Title: Environmental Specialist
Signature: Jorde Jambach	Date: 01/24/2020
email: Lynda.Laumbach@wpxenergy.com	Telephone: (575)725-1647
OCD Only	
Received by: Victoria Venegas	Date: 02/03/2020