

Venegas, Victoria, EMNRD

From: Hamlet, Robert, EMNRD
Sent: Wednesday, April 24, 2019 9:22 AM
To: Adrian Baker
Cc: Ashley Ager; Littrell, Kyle; Bratcher, Mike, EMNRD; Venegas, Victoria, EMNRD; caweaver@blm.gov; jamos@blm.gov; Billings, Bradford, EMNRD; 'jamos@blm.gov'; McKinney, Deborah
Subject: RE: Urgent - Work Plan - JRU 10/2RP-3179, 2RP-3464, and 2RP-5243

Adrian,

I'm glad that you removed the tank battery. The depth of contamination on this site is significant. A couple of things need to be addressed. First, the OCD needs soil samples taken on the boreholes at 5 ft increments to a depth the organics are under the limit. We need a clearer picture of the whole interval, not just at 20 and 42 ft. Essentially, the site hasn't been fully delineated if the bottom sample is still "hot". Second, the depth of the contamination on this site might require close inspection of the tanks to verify their durability.

Please let me know if you have any questions.

Thanks,

Robert J Hamlet
State of New Mexico
Energy, Minerals, and Natural Resources
Oil Conservation Division
811 S. First St., Artesia NM 88210
(575) 840-5963
Robert.Hamlet@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: Adrian Baker <abaker@ltenv.com>
Sent: Friday, April 12, 2019 3:25 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; caweaver@blm.gov; jamos@blm.gov
Cc: Ashley Ager <aager@ltenv.com>; Littrell, Kyle <Kyle_Littrell@xtoenergy.com>
Subject: [EXT] Urgent - Work Plan - JRU 10/2RP-3179, 2RP-3464, and 2RP-5243
Importance: High

All,

Attached is a Work Plan for a recent release and two historical releases at JRU 10/2RP-3179, 2RP-3464, and 2RP-5243. XTO removed the tank battery and needs to replace the tanks as soon as possible for production purposes. Can you please review as quickly as possible?

Thank you



Adrian Baker

Project Geologist/Office Manager

432.894.5641 *cell*

432.704.5178 *direct*

3300 N "A" Street, Building 1, Unit 103, Midland, TX 79705

www.ltenv.com



Think before you print. [Click for our email disclosure.](#)