Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103		
Office District I	Energy, Minerals and Natural Resources		Revised June 10, 2003		
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.	(2500
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSER'	VATION DIV	ISION	30-005-63590 5. Indicate Type of Lease	
District III	1220 South St. Francis Dr.		STATE X	FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			6. State Oil & Gas Lea	
1220 S. St. Francis Dr., Santa Fe, NM		,		o. State on & Gas Let	430 140.
87505			VO-5534		
SUNDRY NOTICE	S AND REPORTS O	N WELLS		7. Lease Name or Uni	t Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					
PROPOSALS.)	ION FOR PERMIT" (FOR	CM C-101) FOR SU	JH	Value BCV	State Com
1. Type of Well:	RECEIVED			8. Well Number	
Oil Well Gas Well X	Other	REC	FIVED	1	
2. Name of Operator		MAV	6 2004	9. OGRID Number	
Yates Petroleum Corporation			025575		
3. Address of Operator			10. Pool name or Wildcat		
105 S. 4 th Street, Artesia, NM 88	88210		Undes. Foor Ranch Pre-Permian, North		
4. Well Location					
11.11.1	0 . 0 . 1	9 4 4		000 0 0	
Unit Letter O: 990	feet from the	South 1	ine and 1	980 feet from the	East line
Section 2	Township	8S Range	26E	NMPM Chaves	County
Section 2	Township	os Kange		INIVITIVI CHAVES	County
	1. Elevation (Show w	hether DR, RKE	, RT, GR, etc.		
3827'GR					
12. Check App	propriate Box to Ir	ndicate Natur	e of Notice,	Report or Other Dat	a
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL					JG AND ANDONMENT
PULL OR ALTER CASING MULTIPLE CASING TEST AN					ANDONIVILIAT
_ (COMPLETION	CE	MENT JOB		
OTHER:			ICD: Ot-	41am On	Test 1
	1 (61 1		-	tion Operations	X
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion					
or recompletion.					
4/21/04 Perforate Silvrian 5607' 5726	S' (116)				
4/21/04 – Perforate Silurian 5697'-5726' (116). 4/22/04 – Acidize Silurian with 1000g 20% IC acid.					
4/28/04 – Shoot 4 squeeze holes at 4590'. Break circulation around 7" and 9-5/8" surface – 4 BPM at 600#. Re-cemented with 300 sx					
Pecos Slope Lite. WOC. Run GR/CBL/CCL from 4503' up to 3620' TOC. Perforate Abo at 4476'-4692' (92). Spotted 2500g 7-1/2%					
IC HCL spearhead acid across perfs. Spotted at 4706'.					
5/6/04 - Frac Abo with 55Q CO2 foamed 35# x-linked gel frac. Total fluid 1564 bbls, CO2 240 tons, sand 314,000# 16/80 Brady.					
•			•	, ,	
		·			
I hereby certify that the information abo	we is true and comple	ete to the best of	my knowledg	e and belief.	
Λ' 1					
I hereby certify that the information about SIGNATURE:				e and belief. se Supervisor DAT	E: <u>May 24, 2004</u>
SIGNATURE: Jina L		ΓΙΤLE:_Regulat	ory Compliand	e Supervisor DAT	
SIGNATURE:			ory Compliand	e Supervisor DAT	E: <u>May 24, 2004</u> one No. 505-748-1471
SIGNATURE:	uerta 1	ΓΙΤLE:_Regulat	ory Compliand	e Supervisor DAT	
SIGNATURE:		ΓΙΤLE:_Regulat	ory Compliand	nm.com Telepho	