

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer 00, Artesia, NM 88210

DISTRICT III
1000 Rio Brator Rd., Aztec, NM 87410

WELL API NO.
30-015-02290

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

East Millman Unit

1. Type of Well:

Oil
Well ☒

Gas
Well ☐

Other ☐

RECEIVED

2. Name of Operator

SDX Resources, Inc.

MAR 22 2004

8. Well No.

162

3. Address of Operator

P.O. Box 5061, Midland, TX 79704

OCD-ARTESIA

9. Pool name or Wildcat

Millman, YT-7R, East (46555)

4. Well Location

Unit Lease H : 1650 Feet From The North Line and 660 Feet From The East Line

Section

22

Township

19S

Range

28E

NMMPM

Eddy

County

10. Elevation (Show whether OF, RKB, RT, CR, etc.)
3387' CR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 3-10-04 1. MIRU.
2. LD rods & pump, fish tbg.
3. Go in hole w/ tbg. & spot 25 sx cmt. @ 1690'.
3-11-04 4. Did not tag TOC, mix & spot 25 sx cmt. WOC & tag @ 1436'.
5. Perf. well @ 580', sqz. 100 sx cmt.
3-12-04 6. Tag TOC @ 340'.
7. Perf. @ 50' sqz. 35 sx cmt. to circ. cmt. to surface.
8. Cmt. @ surface inside & outside 4-1/2". RDMO.
9. Install dry hole marker, & clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Roger Massey

TITLE

Agent

DATE

3-16-04

TYPE OR PRINT NAME

TELEPHONE NO.

(432) 530-0907

(This space for State Use)

APPROVED BY

TITLE

DATE

JUN 25 2004



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop
Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

24 March 2004

SDX Resources, Inc...
P.O. Box 5061
Midland, Tx. 79704

Form C-103 Report of Plugging for your EAST MILLMAN UNIT # 162 Unit H-22-19-28 API 30-015-02290

Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☐ 1. All pits have been filled and leveled.
- ☐ 2. Rat hole and cellar have been filled and leveled.
- ☐ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☐ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☐ 5. The dead men and tie downs have been cut and removed.
- ☐ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☐ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Name

Van Barton
Field Rep. II