

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised May 08, 2003

WELL API NO. 30.015.21828
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. E-5313
7. Lease Name or Unit Agreement Name: EMPIRE ABO UNIT 'L'
8. Well No. 131
9. OGRID Number 000778
10. Pool name or Wildcat EMPIRE ABO
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3529.2' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other	RECEIVED JUN 22 7/11/14 OCC. ARTESIA
2. Name of Operator BP America Production Company	
3. Address of Operator P.O. Box 1089 Eunice NM 88231	
4. Well Location Unit Letter M : 100 feet from the S line and 100 feet from the W line Section 2 Township 18S Range 27E NMPM County EDDY	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3529.2' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

TD: 6210' PED: 6127' PERFS: 5718-5734' (COVERED BY CIBP)

MIRUPU. NDWH. NUBOP. POH W/1 JT. 2-3/8" TBG.

PU 2-3/8" WS & TALLY IN HOLE. TAG TOC OF CIBP @ 5693'.

SPOT 10 SKS CMT ON TOP OF CIBP.

CIRC HOLE W/9.5# KCL MUD TO SURF. PRESS TEST CSG TO 300#.

PUH TO 3706'. SPOT 35 SKS CMT (100' PLUG). WOC. TAG & RECORD TOC

POH TO 553'. SPOT 35 SKS CMT (100' PLUG). WOC. TAG & RECORD TOC.

PUH TO 60'. SPOT 10 SKS CMT TO SURF. WOC 24 HRS. TAG. FILL TO TOP IF NECESSARY.

CUT OFF WH & ANCHORS. INSTALL DRY HOLE MARKER. CLEAN LOCATION. RDPV.

Steel Pits

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Staff Support DATE 06.18.04

Type or print name Kellie D. Murrish Telephone No. 505.394.1649

(This space for State use)

APPROVED BY [Signature] TITLE Field Inspector DATE 6/29/07

Conditions of approval, if any:

WELLBORE SCHEMATIC

