Submit 3 Copies To Appropriate District	State of New Me	exico	Form C-103
Office District I	Energy, Minerals and Natural Resources		Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II	OIL CONSERVATION DIVISION		30-015-23647
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE 🔀
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87	/303	6. State Oil & Gas Lease No.
87505			
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name:			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUGBACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			
PROPOSALS.)	ICATION FOR PERMIT" (FORM C-1019) FO	OR SUCH " (9,2)	
1. Type of Well:	\D\'	4 3/	
Oil Well Gas Well	Other Water Injection Well	7 2000 EV	Ballard
2. Name of Operator	50 R	PECE WOOD SA	8. Well No.
Pecos Production Company	\∞ OCD	PECEIVED 324	24-5
3. Address of Operator	\\.0	THIESIA NOT!	9. Pool name or Wildcat
400 W. Illinois, Ste 1070, Midlan	d, TX 79701	459/	Loco Hills Grayburg SA
4. Well Location			
1505 520 2/00			
Unit Letter 2 1: 19	feet from the South	line and _1780	feet from theEastline
Section 5	Township 100	D AOT	ATHERNA TO III
Section 3	Township 18S	Range 29E	NMPM Eddy County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF I	Appropriate Box to malcate N NTENTION TO:		
PERFORM REMEDIAL WORK		1	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRIL	LING OPNS. PLUG AND
_		COMMENCE DIVIE	ABANDONMENT
PULL OR ALTER CASING	,	CASING TEST AN	
	COMPLETION	CEMENT JOB	
OTHER:	П	OTHER:	п
		į.	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or			
recompilation.			
2/3/03 - Open vlv on tbg & relieve press. Rls pkr & TOOH. TIH & tag cmt @ 150'. Perf csg @ 60'. TIH w/pkr to 15' &			
set. Break circ to surf & cmt outside of 4 1/2" & between 8 5/8" csg to surf w/45 sxs. SD, rls pkr & TOOH. Fill csg up			
to 5' from surf w/cmt. Well P&A'd. RDMO Welder cut off WH & installed marker.			
			. 43
			Per 8 1 3
			(10)
			7
I hereby certify that the information	shove is true and complete to the be	est of my knowledge	and haliaf
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE / / / / / / / / / / / / / / / / / / /	Surrent TITLE B	Engineer Tech	DATE 2/17/03
	_	J	
Type or print name Dora Bustamante Telephone No. (915) 620-8480			
(This space for State use)	200	A -11/	77
ADDODOUGED DAY		July He	P MAR 2 1 2003
APPPROVED BY	TITLE		DATE - 2003
Conditions of approval, If any.	• •	,	į