Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

Expires January 31, 2004

			10 0- 4004	ا احم		
\$	SUNDRY NOTICES AN	5: Lease Serial No.				
	Do not use this form for pr	ω/ LC-047269A				
an	abandoned well. Use Form	3160-3 (APD) for such	PELLS OCD - ARTESIA PROPERTY OF THE PROPERTY O	6. If Indian, Allottee or Tribe Name		
SUBMIT IN	TRIPLICATE - Othe	7 If Unit or CA/Agreement, Name and/or No.				
1 Type of Well		8910085280				
	704	8. Well Name and No.				
X Oil well Gas Well	Other	o. Well Name and No.				
2 Name of Operator	- Compandian	WEST LOCO HILLS UNIT TRACT 1 #3				
3a. Address 3b. Phone No.(include area code)		de area code)	30-015-04492			
105 S.4th St-Arte	sia NM 88210	505-748-147	•	10. Field and Pool, or Exploratory Area		
		-				
4 Location of Well UNIT L 980' FSL, 660	(Footage, Sec.,T.,R.,M., Of FWL SEC, 7-T18S-F	LOCO HILLS QUEEN-GRAYBURG-S/A 11. County or Parish, State				
5.411 2 555 1 52, 555	020.711007			EDDY, NM		
12. CHECK APPRO	PRIATE BOX(ES) TO	O INDICATE NAT	TURE OF NOTICE, REPO	ORT, OR OTHER DATA		
TYPE OF SUBMISSION		TYPE OF ACTION				
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off		
	Alter Casing	Fracture Treat	Reclamation	Well Integrity		
Subsequent Report	Casing Repair	New Construction	Recomplete	Other		
	Change Plans	Plug and Abandon	Temporarily Abandon			
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal			
If the proposal is to deepen direct Attach the Bond under which the value following completion of the involved	tionally ro recomplete horizontally, work will be performed or provide ad operations. If the operation resinal Abandonment Notices shall borfinal inspection.)	give subsurface locations a e the Bond no. on file with ults in a muliple completion be filed only after all requir	ed starting date of any proposed work and nd measured and true vertical depths of a BLM/BIA. Required subsequent reports or recompletion in a new interval, a For rements, including reclamation, have co	ll perinent markers and zones. s shall be filed within 30 days. m 3160-4 shall be filed once		
Call BLM 24 hours before co	mmencing operations.					
Call OCD 24 hours before co	0 ,					
	• 1	e attempted. TOH w/	2-7/8" tubing & production equi	pment.		
•		•	P, load hole w/ plugging mud. Ke	•		
	•	0. 0	, load hole w/ plugging mad. IN	SOP WORLDONG		
loaded w/ mud. Spot 30 sk Class C cement plug from 2355'-2655' - POH.						

- 3. TIH w/ W/L to perforate casing w/ casing guns 6 shots @ 1225' & perf casing w/ 6 shots @ 477'.
- 4. TIH w/ WL WL, set cement retainer @ 1125', TOH. TIH w/ tubing, load hole w/ mud, sting into retainer & establish injection rate. Squeezw w/ 75 sx Class C cement; leave 35' cement on top
- 5. ND BOP'S, TIH w/ WL, set cement retainer @ 377', TOH. TIH w/ tbg, load hole w/ mud. Sting in to retainer, open all valves on bradenhead & establish circ. Squeeze w/ 135 sx Class C cement with 2% CaCl2 from near surface to 477'; leave 35' cement on retainer.

6. TOH w/ tb	g. If circ not established during this stage, WOC, RU WL to perf ca	sg w/ 4 holes @ 325' & tie	(continued)
14 I hereby ce	rtify that the foregoing is true and correct	Title	
Name	(Printed/Typed) DONNA CLACK	REGULATORY COMPLIANCE TECH	
Signature	Aonna Clarker. Market	Date <i>March 27, 2003</i>	
5.00 mg/mg/ 50.00 mg/mg/	THIS SPACE FOR EDERAL OR STATE O	FFICEUSE	
Approved by		Title	Date
Conditions of app	proval, if any, are attached. Approval of this notice does not warrant or		
certify that the app	plicant holds legal or equitable title to those rights in the subject lease	Office	
Which would entit	tle the applicant to conduct operations thereon.		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willbully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

continued:

WLHU TRACT 1 #3 Sec 7-18S-30E 1980' FSL 660' FWL Eddy County, NM

on to 5.5" csg & establish circ; attempt to circ cement to surface w/ an additional 60 sx Class C cement w/ 2% CaCl2. 7. Spot 15 sk Class C cement plug @ surface.

- 8. Remove all surface equipment & weld dry hole marker per regulations.